LAKESIDE AUTOWORKS

REPAIR ESTIMATE

Estimate no.: EST-7734

Customer: Yuki Schmidt

Vehicle: 2013 BMW X6

Description of repair Amount

Fender: $8,075.00

Front bumper cover: $5,599.00

Hood panel: $7,324.00

Front grille: $11,602.00

Paint and materials: $5,362.00

Body labor: $7,188.00

Total estimate: $45,150.00