MIDWEST COLLISION CENTER

REPAIR ESTIMATE

Estimate no.: EST-8326

Customer: Tariq Xu

Vehicle: 2015 Mercedes ML350

Description of repair Amount

Radiator support: $1,528.00

Front bumper cover: $1,877.00

Headlamp assembly: $746.00

Front grille: $1,680.00

Body labor: $1,259.00

Total estimate: $7,090.00