HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-1333

Customer: Aisha Vasquez

Vehicle: 2016 Saab 95

Description of repair Amount

Front bumper cover: $1,546.00

Radiator support: $1,355.00

Front grille: $1,148.00

Hood panel: $686.00

Shop supplies: $1,556.00

Body labor: $1,529.00

Total estimate: $7,820.00