EAGLE BODY & PAINT

REPAIR ESTIMATE

Estimate no.: EST-2517

Customer: Robert Okafor

Vehicle: 2010 Mercedes ML350

Description of repair Amount

Radiator support: $989.00

Headlamp assembly: $2,596.00

Shop supplies: $3,115.00

Total estimate: $6,700.00