EAGLE BODY & PAINT

REPAIR ESTIMATE

Estimate no.: EST-3183

Customer: Chloe Vasquez

Vehicle: 2015 Audi A5

Description of repair Amount

Rear bumper cover: $1,603.00

Quarter panel: $3,830.00

Tail lamp assembly: $1,757.00

Shop supplies: $2,190.00

Total estimate: $9,380.00