HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-3997

Customer: Samuel Nguyen

Vehicle: 2014 Ford F150

Description of repair Amount

Hood panel: $364.00

Headlamp assembly: $512.00

Fender: $1,243.00

Paint and materials: $1,249.00

Shop supplies: $1,372.00

Total estimate: $4,740.00