PHOTO LOG

Photo 1: close view of damage, rear body panel.

Photo 2: close view of damage, tail lamp assembly.

Photo 3: close view of damage, body labor.