SUMMIT COLLISION

REPAIR ESTIMATE

Estimate no.: EST-5810

Customer: Brian Fischer

Vehicle: 2014 Mercedes ML350

Description of repair Amount

Rocker panel: $923.00

Rear door panel: $1,029.00

Side mirror: $374.00

Front door panel: $1,009.00

Shop supplies: $426.00

Frame and alignment: $709.00

Total estimate: $4,470.00