HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-8215

Customer: Leila Brennan

Vehicle: 2014 Saab 92x

Description of repair Amount

Front bumper cover: $1,565.00

Headlamp assembly: $1,479.00

Hood panel: $2,038.00

Fender: $1,979.00

Body labor: $1,049.00

Total estimate: $8,110.00