LAKESIDE AUTOWORKS

REPAIR ESTIMATE

Estimate no.: EST-1296

Customer: Fatima Underwood

Vehicle: 2016 Toyota Highlander

Description of repair Amount

Quarter panel: $6,370.00

Rocker panel: $5,846.00

Door glass: $1,395.00

Front door panel: $2,285.00

Paint and materials: $3,634.00

Total estimate: $19,530.00