EAGLE BODY & PAINT

REPAIR ESTIMATE

Estimate no.: EST-2073

Customer: Robert Underwood

Vehicle: 2024 Saab 93

Description of repair Amount

Quarter panel: $2,141.00

Rear body panel: $2,025.00

Tail lamp assembly: $1,078.00

Rear bumper cover: $1,378.00

Paint and materials: $2,208.00

Total estimate: $8,830.00