LAKESIDE AUTOWORKS

REPAIR ESTIMATE

Estimate no.: EST-6180

Customer: Daniel Xu

Vehicle: 2016 Mercedes C300

Description of repair Amount

Hood panel: $1,445.00

Fender: $3,107.00

Paint and materials: $2,858.00

Total estimate: $7,410.00