SUMMIT COLLISION

REPAIR ESTIMATE

Estimate no.: EST-6476

Customer: Hannah Schmidt

Vehicle: 2015 Chevrolet Malibu

Description of repair Amount

Headlamp assembly: $2,308.00

Front bumper cover: $3,195.00

Fender: $1,149.00

Shop supplies: $1,148.00

Total estimate: $7,800.00