LAKESIDE AUTOWORKS

REPAIR ESTIMATE

Estimate no.: EST-8400

Customer: Omar Fischer

Vehicle: 2011 Toyota Camry

Description of repair Amount

Front bumper cover: $839.00

Radiator support: $537.00

Fender: $1,605.00

Hood panel: $1,691.00

Frame and alignment: $1,346.00

Body labor: $602.00

Total estimate: $6,620.00