Prerequisites to run EX5:

1. Study Part File Curve Tags

- Required input lines/curves should be tagged manually by name as below.
- In main view bottom side (below center line) both supporting feet centerlines should be tagged



