Show all of your work on this assignment and answer each question fully in the given context.

If you cannot submit your homework in the class, you can drop it at my office door in 3220 Snedecore Hall by Thursday at 03:30 PM.

In this homework, you CAN use JMP to plot the data whenever it is asked in the question.

Please staple your assignment and write your name!

1. [Ch 3, Exercise 8, pg. 116] Back to problem 5 of homework two, the accompanying data are the times to failure (in millions of cycles) of high-speed turbine engine bearings made out of two different compounds. These were taking from "Analysis of Single Classification Experiments Based on Censored Samples from the Two-parameter Weibull Distribution" by J. I. McCool (*The Journal of Statistical Planning and Inference*, 1979).

$compound_1$	3.03	5.53	5.60	9.30	9.92	12.51	12.95	15.21	16.04	16.84
$compound_2$	3.19	4.26	4.47	4.53	4.67	4.69	5.78	6.79	9.37	12.75

- (a) Plot a side-by-side boxplot of the two compounds.[10 pts]
- (b) Find all quantiles of compound 1 and use Normal quantile table attached to this homework to find the corresponding normal quantiles[10 pts] hint This part is similar to what we did in class working on ch 3 handout.
- (c) Using the results in part b, plot theoretical Normal QQ-plot against quantiles of compound 1.[10 pts]
- (d) Using the theoretical Normal quantile plot in part c, what can we say about the shape and distribution of compound 2 data? [5 pts]
- (e) Give the coordinates of the upper right point that would appear on a regular graph paper. Also, give the coordinates of the lower left point that would appear on a normal plot of the compound 2 data. [5 pts]
- 2. Calculate the sample mean and sample variance for the following samples:
 - (a) Sample 1: -1.05, -1.0, -0.5, 0.15, 0.6, 0.65, 0.7, 1.25 [5 pts]
 - (b) Sample 2: -2.1, -2.0, -1.0, 0.3, 1.2, 1.3, 1.4, 2.5 [5 pts]
- 3. Mechanical engineers were interested in studying the effects of 2 chemical compounds (low Ca, high Ca) and 3 uni-axial pressure (P1, P2, P3) on metal bars lifetime. A total of 12 specimen were assigned to the possible combinations with two metal bars in each treatment. The lifetime of the bars were recorded after each run of the experiment.
 - (a) How many possible combinations of *compound* ×*pressure* are there available for a full factorial study? Draw a table for this design to get full credit.[5 pts]
 - (b) What is the response variable in this study? [2 pts]
 - (c) What are experimental variables in this study? [2 pts]
 - (d) What type of experimental variables are they in part 3 above? (Be careful with this question, we already know they are experimental variables and not response variable) [2 pts]

Spring 2020 Page 1 of ??

(e) For this full factorial study with two factors chemical compounds and uni-axial pressure, the six experimental runs are labeled as:

No. 1: low-P1, No. 2: low-P2, No. 3: low-P3,

No. 4: high- P1, No. 5: high- P2, and No. 6: high- P3.

Based on the following random digits

49502 18963 63920 39544 25804

Which experiment should be done last?[4 pts]

4. JMP assignment: chapter 3 section 2 problem 2 page 92

Using the data of two turbin suppliers companies below, answer the questions using JMP.

Suplier I	Suplier II
0.52	0.89
0.37	0.99
0.92	1.45
2.89	1.47
3.62	1.58
0.65	2.27

- (a) Provide a scatter plot for the two data sets. [10 pts]
- (b) Plot a Normal QQ-plot of the supplier I data and interpret the shape and distribution of supplier I data.[5 pts]
- (c) Plot a Normal QQ-plot of the supplier II data and interpret the shape and distribution of supplier II data.[5 pts]

Total: 85 pts

Spring 2020 Page 2 of ??

Standard Normal Probabilities




Table entry for \boldsymbol{z} is the area under the standard normal curve to the left of \boldsymbol{z} .

z	.00	.01	.02	.03	.04	.05	.06	.07	.08	.09
-3.4	.0003	.0003	.0003	.0003	.0003	.0003	.0003	.0003	.0003	.0002
-3.3	.0005	.0005	.0005	.0004	.0004	.0004	.0004	.0004	.0004	.0003
-3.2	.0007	.0007	.0006	.0006	.0006	.0006	.0006	.0005	.0005	.0005
-3.1	.0010	.0009	.0009	.0009	.0008	.0008	.0008	.0008	.0007	.0007
-3.0	.0013	.0013	.0013	.0012	.0012	.0011	.0011	.0011	.0010	.0010
-2.9	.0019	.0018	.0018	.0017	.0016	.0016	.0015	.0015	.0014	.0014
-2.8	.0026	.0025	.0024	.0023	.0023	.0022	.0021	.0021	.0020	.0019
-2.7	.0035	.0034	.0033	.0032	.0031	.0030	.0029	.0028	.0027	.0026
-2.6	.0047	.0045	.0044	.0043	.0041	.0040	.0039	.0038	.0037	.0036
-2.5	.0062	.0060	.0059	.0057	.0055	.0054	.0052	.0051	.0049	.0048
-2.4	.0082	.0080	.0078	.0075	.0073	.0071	.0069	.0068	.0066	.0064
-2.3	.0107	.0104	.0102	.0099	.0096	.0094	.0091	.0089	.0087	.0084
-2.2	.0139	.0136	.0132	.0129	.0125	.0122	.0119	.0116	.0113	.0110
-2.1	.0179	.0174	.0170	.0166	.0162	.0158	.0154	.0150	.0146	.0143
-2.0	.0228	.0222	.0217	.0212	.0207	.0202	.0197	.0192	.0188	.0183
-1.9	.0287	.0281	.0274	.0268	.0262	.0256	.0250	.0244	.0239	.0233
-1.8	.0359	.0351	.0344	.0336	.0329	.0322	.0314	.0307	.0301	.0294
-1.7	.0446	.0436	.0427	.0418	.0409	.0401	.0392	.0384	.0375	.0367
-1.6	.0548	.0537	.0526	.0516	.0505	.0495	.0485	.0475	.0465	.0455
-1.5	.0668	.0655	.0643	.0630	.0618	.0606	.0594	.0582	.0571	.0559
-1.4	.0808	.0793	.0778	.0764	.0749	.0735	.0721	.0708	.0694	.0681
-1.3	.0968	.0951	.0934	.0918	.0901	.0885	.0869	.0853	.0838	.0823
-1.2	.1151	.1131	.1112	.1093	.1075	.1056	.1038	.1020	.1003	.0985
-1.1	.1357	.1335	.1314	.1292	.1271	.1251	.1230	.1210	.1190	.1170
-1.0	.1587	.1562	.1539	.1515	.1492	.1469	.1446	.1423	.1401	.1379
-0.9	.1841	.1814	.1788	.1762	.1736	.1711	.1685	.1660	.1635	.1611
-0.8	.2119	.2090	.2061	.2033	.2005	.1977	.1949	.1922	.1894	.1867
-0.7	.2420	.2389	.2358	.2327	.2296	.2266	.2236	.2206	.2177	.2148
-0.6	.2743	.2709	.2676	.2643	.2611	.2578	.2546	.2514	.2483	.2451
-0.5	.3085	.3050	.3015	.2981	.2946	.2912	.2877	.2843	.2810	.2776
-0.4	.3446	.3409	.3372	.3336	.3300	.3264	.3228	.3192	.3156	.3121
-0.3	.3821	.3783	.3745	.3707	.3669	.3632	.3594	.3557	.3520	.3483
-0.2	.4207	.4168	.4129	.4090	.4052	.4013	.3974	.3936	.3897	.3859
-0.1	.4602	.4562	.4522	.4483	.4443	.4404	.4364	.4325	.4286	.4247
-0.0	.5000	.4960	.4920	.4880	.4840	.4801	.4761	.4721	.4681	.4641

Standard Normal Probabilities




Table entry for \boldsymbol{z} is the area under the standard normal curve to the left of \boldsymbol{z} .

	.00	.01	.02	.03	.04	.05	.06	.07	.08	.09
0.0	.5000	.5040	.5080	.5120	.5160	.5199	.5239	.5279	.5319	.5359
0.1	.5398	.5438	.5478	.5517	.5557	.5596	.5636	.5675	.5714	.5753
0.2	.5793	.5832	.5871	.5910	.5948	.5987	.6026	.6064	.6103	.6141
0.3	.6179	.6217	.6255	.6293	.6331	.6368	.6406	.6443	.6480	.6517
0.4	.6554	.6591	.6628	.6664	.6700	.6736	.6772	.6808	.6844	.6879
0.5	.6915	.6950	.6985	.7019	.7054	.7088	.7123	.7157	.7190	.7224
0.6	.7257	.7291	.7324	.7357	.7389	.7422	.7454	.7486	.7517	.7549
0.7	.7580	.7611	.7642	.7673	.7704	.7734	.7764	.7794	.7823	.7852
8.0	.7881	.7910	.7939	.7967	.7995	.8023	.8051	.8078	.8106	.8133
0.9	.8159	.8186	.8212	.8238	.8264	.8289	.8315	.8340	.8365	.8389
1.0	.8413	.8438	.8461	.8485	.8508	.8531	.8554	.8577	.8599	.8621
1.1	.8643	.8665	.8686	.8708	.8729	.8749	.8770	.8790	.8810	.8830
1.2	.8849	.8869	.8888	.8907	.8925	.8944	.8962	.8980	.8997	.9015
1.3	.9032	.9049	.9066	.9082	.9099	.9115	.9131	.9147	.9162	.9177
1.4	.9192	.9207	.9222	.9236	.9251	.9265	.9279	.9292	.9306	.9319
1.5	.9332	.9345	.9357	.9370	.9382	.9394	.9406	.9418	.9429	.9441
1.6	.9452	.9463	.9474	.9484	.9495	.9505	.9515	.9525	.9535	.9545
1.7	.9554	.9564	.9573	.9582	.9591	.9599	.9608	.9616	.9625	.9633
1.8	.9641	.9649	.9656	.9664	.9671	.9678	.9686	.9693	.9699	.9706
1.9	.9713	.9719	.9726	.9732	.9738	.9744	.9750	.9756	.9761	.9767
2.0	.9772	.9778	.9783	.9788	.9793	.9798	.9803	.9808	.9812	.9817
2.1	.9821	.9826	.9830	.9834	.9838	.9842	.9846	.9850	.9854	.9857
2.2	.9861	.9864	.9868	.9871	.9875	.9878	.9881	.9884	.9887	.9890
2.3	.9893	.9896	.9898	.9901	.9904	.9906	.9909	.9911	.9913	.9916
2.4	.9918	.9920	.9922	.9925	.9927	.9929	.9931	.9932	.9934	.9936
2.5	.9938	.9940	.9941	.9943	.9945	.9946	.9948	.9949	.9951	.9952
2.6	.9953	.9955	.9956	.9957	.9959	.9960	.9961	.9962	.9963	.9964
2.7	.9965	.9966	.9967	.9968	.9969	.9970	.9971	.9972	.9973	.9974
2.8	.9974	.9975	.9976	.9977	.9977	.9978	.9979	.9979	.9980	.9981
2.9	.9981	.9982	.9982	.9983	.9984	.9984	.9985	.9985	.9986	.9986
3.0	.9987	.9987	.9987	.9988	.9988	.9989	.9989	.9989	.9990	.9990
3.1	.9990	.9991	.9991	.9991	.9992	.9992	.9992	.9992	.9993	.9993
3.2	.9993	.9993	.9994	.9994	.9994	.9994	.9994	.9995	.9995	.9995
3.3	.9995	.9995	.9995	.9996	.9996	.9996	.9996	.9996	.9996	.9997
3.4	.9997	.9997	.9997	.9997	.9997	.9997	.9997	.9997	.9997	.9998