



POWER_LED




16 Mhz Crystal




Place close to MCU


RESET SWITCH





RGB Debug LED



AVR128DB32 MCU




DM542 Out




UPDI Programmer Pins

24V Power Input RS485



MAX485 RS485 Module




Termination resistor only needed in last node



For DRV8825/TMC2130


DRV8825_STEPPER_MOTOR_DRIVER_CARRIER

SPI Interface for TMC2130



Stepper Motor Driver Mount for StepStick


Motor Out




NEMA 17 Motor Section

Interfaces

THERMISTOR



Limit Switch/Hall Effect JST



A1324 Hall Effect Sensor needs Analog Input

Laser Module

