Solid Edge Professional: Sheet Metal

| Time Allotted: | 180 minutes |
|-----------------|-------------|
| 「ime Spent: | 18 minutes |
| Time Remaining: | 162 minutes |

The times above will update when you begin the next section of the exam.

<u>Solid Edge Professional Level Certification</u> > <u>Solid Edge Professional Level Exam</u> > <u>Solid Edge Professional: Sheet Metal</u>

| rogress saved | 'ro | gress | saved |
|---------------|-----|-------|-------|
|---------------|-----|-------|-------|

! of 6 Questions answered correctly

'our time: 00:07:27

You have reached 6 of 18 point(s), (33.33%)

View Questions


Click Here to Continue

Vhen placing a new flange, which is not a material side option?

- Bend Inside
- Material Outside
- Material inside
- Bend Outside

Incorrect

Vhich numbered feature represents a Bend Relief?



| 0 | 4 | |
|---|---|--|
| | 3 | |
| 0 | 2 | |
| 0 | 8 | |
| 0 | 1 | |
| 0 | 5 | |
| 0 | 6 | |

Incorrect

Vhich feature is represented as a deformed feature in the flat pattern?

Bead

- Tab
- Contour Flange
- Flange

Incorrect

Vhat command is used to create these Sheet Metal Features?



- Dimple
- Cross Brake
- Drawn Cutout
- Bead

Correct

Vhat command is used to create these Sheet Metal Features?



| | Louver |
|---|--------|
| | |
| 0 | Dimple |
| | |
| | Bead |
| | |
| | |

Correct

Vhich two commands can form a starting feature in Sheet Metal?

Sheet or Gusset

Drawn Cutout

- Tab or Contoured Flange
- Flange or Bend
- Bend or Tab

Incorrect