Solid Edge Professional: Draft

Fime Allotted:180 minutesFime Spent:10 minutesFime Remaining:170 minutes

he times above will update when you begin the next section of the exam.

Solid Edge Professional Level Certification > Solid Edge Professional Level Exam > Solid Edge Professional: Draft

Progress saved.	' ro	gress	saved	١.
-----------------	-------------	-------	-------	----

of 6 Questions answered correctly

'our time: 00:01:13

You have reached 12 of 18 point(s), (66.67%)

View Questions

Click Here to Continue

For long narrow parts like a shaft, what method is used to graphically remove the center portion to fit on a drawing sheet?

- Scale
- Crop
- Add Broken View
- Remove Section

Correct

f you need to move an associated orthogonal view to another location, what option should you select or deselect from the popup menu?

- Disassociate
- Ungroup

	Deselect Maintain Alignment				
0	Deselect cropping				
	Correct				
he co	he command finder in the Draft environment will not find anything for:				
•	Feature library				
0	Surface Texture Symbol				
	Parts List				
0	Maintain Alignment Set				
	Correct				
n the Draft environment, which of the following types of tables cannot be created?					
0	Family of Parts Table				
	Variable Table				
0	Bend Table				
0	Hole Table				
	Correct				
ō pla	o place an exploded view of an assembly on a Drawing Sheet,				
0	the explosion must first be saved in the Assembly file as a configuration				

17/05/2025	Solid Edge 1 Folessional. Plate Crib Certained of Foleness Solivate	
•	select the Explode command from the ERA tab in Draft	
0	right click on the view and select Explode	
0	use the Place Exploded View command	
	Incorrect	
The default text height for dimensions is set in the		
0	File Units Dialog Box	
0	Properties Dialog Box	
•	Options Dialog Box	
0	Styles Dialog Box	
	Incorrect	