





	current state	mest state	out put	wait	
(1)	GoSouth	0000, 0010 GoSouth	PA 00110000	1.55	
		0001,0011 Wait West	PF 0000 0010		
		Olxx Wait Walk South			
2	Wait West	Gowest	PA 01010000	.25s	
_			P= ×02		
(3)	Go West	0000, 0001 Gowest		1,55	
٩		0000,0011 Whit South	PF ×02		
_	101 11 C 11	OIXX WaitWalk West	0.0		
0) Wait South	GoSouth	PA 10001000	.25 s	
_	Wait Walk South	Walk	PF x02		
G. G) Vacity ratio	race	PF ×02	. 255	
_	WaitWalk west	Walh	PA 1000 1000		
6	VOM	1000	PF Y02	. 255	
6)	Walk	FinishWall	PA 10010000	,755	Annual Control of the
0			PF XD8	1135	Chapterin er
(7)	Finish Walk	xx1x GoSouth	PA 10010000	. 755	
G	0000	0,0100 Walk	PF toggle × 02		
	0101	, add to west			
9					
		g			