# **Guidelines Monitoring Report (All Pages)**

Project Number: 100034567

Contact Person: Ashok Balasubramanian

## **Page-by-Page Findings Summary:**

#### Page 1:

- 1. Missing Labels: The Relay symbol on page 1 lacks a nearby label.
- 2. Misclassified Symbol: 'Cable' classification may be incorrect.
- 3. Zone B3 referenced in text but no matching symbol found.
- 4. Symbol detected at (150,0) is far from expected layout region.
- 5. Naming mismatch: '38', 'CT1', and 'K1' unlinked to symbols.
- 6. Confidence inconsistency across similar symbols.

#### Page 2:

- 1. Missing Labels: The Relay symbol on page 2 lacks a nearby label.
- 2. Misclassified Symbol: 'Cable' classification may be incorrect.
- 3. Zone B3 referenced in text but no matching symbol found.
- 4. Symbol detected at (150,0) is far from expected layout region.
- 5. Naming mismatch: '38', 'CT1', and 'K1' unlinked to symbols.
- 6. Confidence inconsistency across similar symbols.

#### Page 3:

- 1. Missing Labels: The Relay symbol on page 3 lacks a nearby label.
- 2. Misclassified Symbol: 'Cable' classification may be incorrect.
- 3. Zone B3 referenced in text but no matching symbol found.
- 4. Symbol detected at (150,0) is far from expected layout region.
- 5. Naming mismatch: '38', 'CT1', and 'K1' unlinked to symbols.
- 6. Confidence inconsistency across similar symbols.

#### Page 4:

- 1. Missing Labels: The Relay symbol on page 4 lacks a nearby label.
- 2. Misclassified Symbol: 'Cable' classification may be incorrect.
- 3. Zone B3 referenced in text but no matching symbol found.

# **Guidelines Monitoring Report (All Pages)**

- 4. Symbol detected at (150,0) is far from expected layout region.
- 5. Naming mismatch: '38', 'CT1', and 'K1' unlinked to symbols.
- 6. Confidence inconsistency across similar symbols.

### Page 5:

- 1. Missing Labels: The Relay symbol on page 5 lacks a nearby label.
- 2. Misclassified Symbol: 'Cable' classification may be incorrect.
- 3. Zone B3 referenced in text but no matching symbol found.
- 4. Symbol detected at (150,0) is far from expected layout region.
- 5. Naming mismatch: '38', 'CT1', and 'K1' unlinked to symbols.
- 6. Confidence inconsistency across similar symbols.