

Report Homework 3


Chayan Dhaddha 19111025 Anuraag Kansara 19111013 Ashwani Bhat 19111019


1. For DA1: The below figure shows the raw sensor measurements of sensor XMEAS(15).







2. For DA2: The below figure shows the raw sensor measurements of sensor XMEAS(5).







3. For Attack SA1: The below figure shows the raw sensor measurements of sensor XMEAS(5).





4. For Attack SA2: The below figure shows the raw sensor measurements of sensor XMEAS(10).





5. For Attack SA3: The below figure shows the raw sensor measurements of sensor XMEAS(9).

