




MOTION DETECTION LIGHT



ASSEMBLY & OPERATION GUIDE

Plug each module into the correct JST port



Setup Steps

- 1 Prepare the Chassis by following the "Steps to Assemble Chassis" on Page 3
- 2 Mount the battery holder on chassis at Position 1 using Velcro
- 3 Mount the PCB Board on the Chassis at Position 2 using Velcro
- 4 Mount the IR Sensor on the Chassis at Position 3 using Velcro
- 5 Connect the IR Sensor to the Sensor JST connector on the PCB board using the 3-pin to 3-pin JST cable
- 6 Mount the LED on the Chassis at Position 5 and connect the LED JST connector to CON1 Connector on the PCB board
- 7 Connect the Reverse JST cable to REV JST connector on the PCB board
- 8 Connect the Battery Holder to the Power JST connector on the PCB board
- 9 Check that all connections are secure before switching on the power




How to Try It

- 1 Switch ON the circuit.
- 2 Make sure the LED is off.
- 3 Wave your hand or move in front of the IR sensor.
- 4 The LED turns on when motion is detected.
- 5 The LED remains off until motion is detected.

1

No Motion

No movement detected



No moving object is detected, so the LED stays OFF.

2

Motion Detected

Movement triggers the light



When motion is detected, the LED turns ON.

Small Projects. Big Possibilities!