iLocate BLE Management Application

Manager Module

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Select...

Search

Time St Today

Today
Last 42 Hours
Last 1 Week

8:00 AM [Dashboard updates every 1 hour]

Refresh

Beacon status

Search By Vehicle ID

Vehicle ID	Assigned	Reporting
10-00683	5	5
10-00423	5	6
10-00374	5	4
10-002[illegible]	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Summary

eported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count:	40
Reported Item Count:	40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00374**

Time St Today

5:10 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374 !	DUKE

Initiate Scan

BLE Scan Report History

Problem Summary: **Beacon Missing**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 03:05 PM	Success	-	4 of 5 !	DUKE
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Failure	Bluetooth OFF	-	DUKE
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	-	-	DUKE
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	4 of 5 !	DUKE
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	5 of 5	DUKE
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	DUKE
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	DUKE
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	DUKE

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	63%	1.5 m
Little Giant Ladder	!	-	-
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Select... Search

Time St Today

8:00 AM [Dashboard updates every 1 hour] Refresh

Beacon status

Search By Vehicle ID

Vehicle ID	Assigned	Reporting
10-00683	5	5
10-00423	5	6
10-00374	5	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count: 40

Reported Item Count: 40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00423**

Time St Today

6:10 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00423 !	ATHEY
10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Failure	-	6 of 5 !	ADAMS !
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	Bluetooth OFF	-	ADAMS
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	6 of 5 !	ADAMS !
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	6 of 5 !	ADAMS !
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	ATHEY
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 07:55 AM	Success	-	5 of 5	ATHEY

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	! ⚙	-	-
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00254**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00423 !	ATHEY
10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Blue Truth Not Reporting;**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 08:20 AM	Success	-	7 of 5 !	ATHEY !
Automatic – By Admin	10/20/ 2017 08:10 AM	Success	-	7 of 5 !	ADAMS !

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Select... Search

Time St Today

8:00 AM [Dashboard updates every 1 hour] Refresh

Beacon status

Search By Vehicle ID

Vehicle ID	Assigned	Reporting
10-00683	5	5
10-00423	5	6
10-00374	5	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count: 40

Reported Item Count: 40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00423**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

	Vehicle #	Assigned Driver
	10-00423 !	ATHEY
	10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Success	-	6 of 5	ADAMS !
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	Bluetooth OFF	-	ADAMS
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	6 of 5	ADAMS !
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	6 of 5	ADAMS !
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	ATHEY
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 07:55 AM	Success	-	5 of 5	ATHEY

Notify Driver | Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	!	-	-
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00254**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00423 !	ATHEY
10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 08:20 AM	Success	-	7 of 5 !	ATHEY
Automatic – By Admin	10/20/ 2017 08:10 AM	Success	-	7 of 5 !	ADAMS

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Select... Search

Time St Today

8:00 AM [Dashboard updates every 1 hour] Refresh

Beacon status

Search By Vehicle ID

Vehicle ID	Assigned	Reporting
10-00683	5	5
10-00423	5	6
10-00374	5	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count: 40

Reported Item Count: 40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00254**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Blue Truth Not Reporting;**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 08:20 AM	Success	-	7 of 5	ATHEY
Automatic – By Admin	10/20/ 2017 08:10 AM	Success	-	7 of 5	ADAMS

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment

	Manger Name	Assigned Driver	Vehicle #	GPS ID	Make	GPS BLE Status	BLE Equipment Status
●	MCCONNEY, RICK	EVAN	10-00683	4562084459	CHEV	Assigned	0
○	MCCONNEY, RICK	ATHEY	10-00423	4562074456	CHEV	Assigned	6
○	MCCONNEY, RICK	ADAMS	10-00254	4562074456	FORD	Assigned	6
○	MCCONNEY, RICK	DUKE	10-00374	4562078849	FORD	Not Assigned	5

View / Update BLE Detail

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00683
GPS BLE Indicator :	Yes
GPS Unit ID:	4562084459
Make:	CHEV
Model:	CH250AD
License:	BL99443
Owner Name	MCCONNEY, RICK
Active Driver	EVAN

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
10-00683	4562084459	GPS	BLE Enable GPS	10/31/2011 10:45 AM	12/31/2037 23:59 PM

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00683
GPS BLE Indicator :	Yes
GPS Unit ID:	4562084459
Make:	CHEV
Model:	CH250AD
License:	BL99443
Owner Name	MCCONNEY, RICK
Active Driver	EVAN

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
10-00683	4562084459	GPS	BLE Enable GPS	10/31/2011 10:45 AM	12/31/2037 23:59 PM
F237D37	AC:23:3F:23:7D:37	Meter	Meter 1.	10/31/2011 10:50 AM	12/31/2037 23:59 PM

Select...
Meter
Little Giant Ladder
Impact Drill
Long Ladder
GPS
Cable Scanner

Select...
Meter 1
Meter 2
Meter 3
Meter 4
Meter 5

Deactivate | Export | Upload .CSV File | Scan | Add | Save

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00683
GPS BLE Indicator :	Yes
GPS Unit ID:	4562084459
Make:	CHEV
Model:	CH250AD
License:	BL99443
Owner Name	MCCONNEY, RICK
Active Driver	EVAN

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
10-00683	4562084459	GPS	BLE Enable GPS	10/31/2011 10:45 AM	12/31/2037 23:59 PM
F238A41	AC:23:3F:23:8A:41	Meter	Meter 1	10/31/2011 10:50 AM	12/31/2037 23:59 PM
F238A42	AC:23:3F:23:8A:42	Littlie Giant Ladder	Littlie Giant Ladder 1	10/31/2011 10:55 AM	12/31/2037 23:59 PM
F238A43	AC:23:3F:23:8A:43	Impact Drill	Impact Drill 1	10/31/2011 10:56 AM	12/31/2037 23:59 PM
F238A44	AC:23:3F:23:8A:44	Meter	Meter 2	10/31/2011 10:57 AM	12/31/2037 23:59 PM

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment

	Manger Name	Assigned Driver	Vehicle #	GPS ID	Make	GPS BLE Status	BLE Equipment Status
●	MCCONNEY, RICK	EVAN	10-00683	4562084459	CHEV	Assigned	5
○	MCCONNEY, RICK	ATHEY	10-00423	4562074456	CHEV	Assigned	6
○	MCCONNEY, RICK	ADAMS	10-00254	4562074456	FORD	Assigned	6
○	MCCONNEY, RICK	DUKE	10-00374	4562078849	FORD	Not Assigned	5

View / Update BLE Detail

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment

Manger Name	Assigned Driver	Vehicle #	GPS ID	Make	GPS BLE Status	BLE Equipment Status
MCCONNEY, RICK	EVAN	10-00683	4562084459	CHEV	Assigned	0
MCCONNEY, RICK	ATHEY	10-00423	4562074456	CHEV	Assigned	1
MCCONNEY, RICK	ADAMS	10-00254	4562074456	FORD	Assigned	1
MCCONNEY, RICK	DUKE	10-00374	4562078849	FORD	Not Assigned	0

View / Update BLE Detail

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00254
GPS BLE Indicator :	No
GPS Unit ID:	4562074456
Make:	Ford
Model:	SZ250AD
License:	AQ66944
Owner Name	MCCONNEY, RICK
Active Driver	ADAMS

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F237D36	AC:23:3F:23:7D:36	GPS	BLE Enable GPS	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D37	AC:23:3F:23:7D:37	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D38	AC:23:3F:23:7D:38	Littlie Giant Ladder	Littlie Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D39	AC:23:3F:23:7D:39	Impact Drill	Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D40	AC:23:3F:23:7D:40	Meter	Meter 2	10/31/2011 00:00 AM	12/31/2037 23:59 PM

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00254
GPS BLE Indicator :	No
GPS Unit ID:	4562074456
Make:	Ford
Model:	SZ250AD
License:	AQ66944
Owner Name	MCCONNEY, RICK
Active Driver	ADAMS

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F237D36	AC:23:3F:23:7D:36	GPS	BLE Enable GPS	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D37	AC:23:3F:23:7D:37	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D38	AC:23:3F:23:7D:38		Little Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D39	AC:23:3F:23:7D:39		Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D40	AC:23:3F:23:7D:40		Meter 2	10/31/2011 00:00 AM	12/31/2037 23:59 PM

Select...
Meter
Little Giant Ladder
Impact Drill
Long Ladder
GPS
Cable Scanner

Deactivate | Export | Upload .CSV File | Scan | Add | Save

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00254
GPS BLE Indicator :	No
GPS Unit ID:	4562074456
Make:	Ford
Model:	SZ250AD
License:	AQ66944
Owner Name	MCCONNEY, RICK
Active Driver	ADAMS

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F237D36	AC:23:3F:23:7D:36	GPS	BLE Enable GPS	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D37	AC:23:3F:23:7D:37	Long Ladder	Long Ladder 1	11/22/2011 00:00 AM	12/31/2037 23:59 PM
F237D38	AC:23:3F:23:7D:38	Little Giant Ladder		10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D39	AC:23:3F:23:7D:39	Impact Drill		10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D40	AC:23:3F:23:7D:40	Meter		10/31/2011 00:00 AM	12/31/2037 23:59 PM

Select...
Long Ladder 1
Long Ladder 2
Long Ladder 3
Long Ladder 4
Long Ladder 5

Deactivate | Export | Upload .CSV File | Scan | Add | Save

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00254**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00254
GPS BLE Indicator :	No
GPS Unit ID:	4562074456
Make:	Ford
Model:	SZ250AD
License:	AQ66944
Owner Name	MCCONNEY, RICK
Active Driver	ADAMS

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F237D36	AC:23:3F:23:7D:36	GPS	BLE Enable GPS	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D37	AC:23:3F:23:7D:37	Long Ladder	Long Ladder 1	11/21/2011 00:00 AM	12/31/2037 23:59 PM
F237D38	AC:23:3F:23:7D:38	Littlie Giant Ladder	Littlie Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D39	AC:23:3F:23:7D:39	Impact Drill	Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F237D40	AC:23:3F:23:7D:40	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Select... Search

Time St Today

8:00 AM [Dashboard updates every 1 hour] Refresh

Beacon status

Search By Vehicle ID

Vehicle ID	Assigned	Reporting
10-00683	5	5
10-00423	5	6
10-00374	5	4
10-002[illegible]	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count:	40
Reported Item Count:	40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00374**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374 !	DUKE
10-00683	EVAN
10-00423 !	ATHEY
10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Beacon Missing**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 03:05 PM	Success	-	4 of 5 !	DUKE
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Failure	Bluetooth OFF	-	DUKE
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	-	-	DUKE
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	4 of 5 !	DUKE
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	5 of 5	DUKE
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	DUKE
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	DUKE
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	DUKE

Notify Driver

Export Scan Report

Map

Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	!	63%	1.5 m
Long Ladder	✓	-	-
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00374**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374 !	DUKE
10-00683	EVAN
10-00423 !	ATHEY
10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Beacon Missing**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 03:05 PM	Success	-	4 of 5 !	DUKE
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Failure	Bluetooth OFF	-	DUKE
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	-	-	DUKE
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	4 of 5 !	DUKE
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	5 of 5	DUKE
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	DUKE
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	DUKE
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	DUKE

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
-			
-			
-			
-			
-			

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00374**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes] Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374	DUKE
10-00683	EVAN
10-00423	ATHEY
10-00254	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Beacon Missing**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – Ignition ON					
Automatic – By Admin					
Automatic – Ignition ON					
Manual - By Technician					
Automatic – End of Job					
Automatic – Ignition ON					
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	DUKE

Notify Driver | Export Scan Report

Message To : DUKE

CC : MCCONNEY, RICK

Duke ,
The scan report identified you have **left** following item(s)

1. Little Giant Ladder

at Location :
Latitude: 31.732216
Longitude: -82.835083

Please collect and initiate BLE Scan of the devices

Thanks,
iLocate Support Team
1 (800) 333 HELP

Cancel | Send

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	!	-	-
Long Ladder	✓	63%	1.5 m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00423**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374 !	DUKE
10-00683	EVAN
10-00423 !	ATHEY
10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Success	-	6 of 5 !	ADAMS !
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	-	-	ADAMS
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	6 of 5 !	ADAMS !
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	6 of 5 !	ADAMS !
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	ATHEY
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 07:55 AM	Success	-	5 of 5	ATHEY

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	!	-	-
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00254**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374	DUKE
10-00683	EVAN
10-00423	ATHEY
10-00254	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – By Admin					

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

Equipment Label : Long Ladder

Beacon Name: F237D37

MAC ID / ESN: AC:23:3F:23:7D:37

Description: Lorem ipsum

End Date/Time: 10/31/2011 00:00 AM

Start Date/Time : 12/31/2037 23:59 PM

Assigned to Vehicle: 10-00423

Last Reported Vehicle : **10-00254 at** 10/20/ 2017 **08:20 AM**

Location : Latitude: 31.732216 Longitude: -82.835083

Cancel

Notify Driver

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00254**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374	DUKE
10-00683	EVAN
10-00423	ATHEY
10-00254	ADAMS

BLE Scan Report History

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – By Admin					

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

Message To : ATHEY; ADAMS

CC : MCCONNEY, RICK

ADAMS ,
The scan report identified you have **additional** following item(s)

1. Long Ladder
2. Impact Drill

Last Reported Vehicle : 10-00254 at 10/20/ 2017 08:20 AM
Location : Latitude: 31.732216 Longitude: -82.835083

The equipment(s) belong to **Vehicle # 10-00423** please pass it the current driver: ATHEY the and initiate BLE Scan of the devices

Thanks,
iLocate Support Team
1 (800) 333 HELP

Cancel | Send

Initiate Scan | Notify Driver | Export Scan Report

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00683**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00374	DUKE
10-00683	EVAN
10-00423	ATHEY
10-00254	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **None**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 03:05 PM	Success	-	5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Success		5 of 5	EVAN
Automatic – By Admin	10/20/ 2017 02:35 PM	Success	-	5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	5 of 5	EVAN
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	5 of 5	EVAN
Automatic – End of Job	10/20/ 2017 11:30 AM	Success		5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	EVAN
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	EVAN

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	95%	.8m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00683**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

	Vehicle #	Assigned Driver
	10-00374 !	DUKE
	10-00683	EVAN
	10-00423 !	ATHEY
	10-00254 !	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **None**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Automatic – By Admin	10/20/ 2017 6:20 PM	Success	-	5 of 5	EVAN
Manual - By Technician	10/20/ 2017 03:05 PM	Success	-	5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Success		5 of 5	EVAN
Automatic – By Admin	10/20/ 2017 02:35 PM	Success	-	5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	5 of 5	EVAN
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	5 of 5	EVAN
Automatic – End of Job	10/20/ 2017 11:30 AM	Success		5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	EVAN

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	95%	.8m
Littlie Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment

	Manger Name	Assigned Driver	Vehicle #	GPS ID	Make	GPS BLE Status	BLE Equipment Status
○	MCCONNEY, RICK	EVAN	10-00683	4562084459	CHEV	Assigned	5
○	MCCONNEY, RICK	ATHEY	10-00423	4562074456	CHEV	Assigned	6
○	MCCONNEY, RICK	ADAMS	10-00254	4562074456	FORD	Assigned	6
●	MCCONNEY, RICK	DUKE	10-00374	4562078849	FORD	Not Assigned	5

View / Update BLE Detail

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00374**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00374
GPS BLE Indicator :	No
GPS Unit ID:	4562078849
Make:	Ford
Model:	AZ760BC
License:	TJ78940
Owner Name	MCCONNEY, RICK
Active Driver	DUKE

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F239C76	AC:23:3F:23:9C:76	Little Giant Ladder	Little Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C77	AC:23:3F:23:9C:77	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C78	AC:23:3F:23:9C:78	Cable Scanner	Cable Scanner 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C79	AC:23:3F:23:9C:79	Impact Drill	Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00374**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00374
GPS BLE Indicator :	No
GPS Unit ID:	4562078849
Make:	Ford
Model:	AZ760BC
License:	TJ78940
Owner Name	MCCONNEY, RICK
Active Driver	DUKE

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F239C76	AC:23:3F:23:9C:76	Little Giant Ladder	Little Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C77	AC:23:3F:23:9C:77	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C78	AC:23:3F:23:9C:78	Cable Scanner	Cable Scanner 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C79	AC:23:3F:23:9C:79	Impact Drill	Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F44		Select	Select	10/31/2011 10:45 AM	12/31/2037 23:59 PM

The value entered above does not match our Beacon Name formatting. Here is a sample Beacon Name: 'F237D36' for your reference

Deactivate | Export | Upload .CSV File | Scan | Add | Save

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00374**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00374
GPS BLE Indicator :	No
GPS Unit ID:	4562078849
Make:	Ford
Model:	AZ760BC
License:	TJ78940
Owner Name	MCCONNEY, RICK
Active Driver	DUKE

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F239C76	AC:23:3F:23:9C:76	Little Giant Ladder	Little Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C77	AC:23:3F:23:9C:77	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C78	AC:23:3F:23:9C:78	Cable Scanner	Cable Scanner 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C79	AC:23:3F:23:9C:79	Impact Drill	Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C80	AC:23:3F:23:9C:80	Select	BLE Enable GPS	10/31/2011 10:45 AM	12/31/2037 23:59 PM

Select...
Meter
Little Giant Ladder
Impact Drill
Long Ladder
GPS
Cable Scanner

Deactivate | Export | Upload .CSV File | Scan | Add | Save

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00374**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00374
GPS BLE Indicator :	No
GPS Unit ID:	4562078849
Make:	Ford
Model:	AZ760BC
License:	TJ78940
Owner Name	MCCONNEY, RICK
Active Driver	DUKE

Beacon Details

Beacon Name	Start Date/Time	End Date/Time
F239C76	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C77	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C78	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C79	10/31/2011 00:00 AM	12/31/2037 23:59 PM
4562078849	10/31/2011 00:00 AM	12/31/2037 23:59 PM

Alert

Are you sure you want to deactivate these Beacon(s)?

Cancel | Yes

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment > Vehicle: **10-00374**

BLE Scan Report

Vehicle Information

Field	Details
VID:	10-00374
GPS BLE Indicator :	No
GPS Unit ID:	4562078849
Make:	Ford
Model:	AZ760BC
License:	TJ78940
Owner Name	MCCONNEY, RICK
Active Driver	DUKE

Beacon Details

Beacon Name	MAC ID / ESN	Label	Description	Start Date/Time	End Date/Time
F239C76	AC:23:3F:23:9C:76	Little Giant Ladder	Little Giant Ladder 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C77	AC:23:3F:23:9C:77	Meter	Meter 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C78	AC:23:3F:23:9C:78	Long Ladder	Cable Scanner 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C79	AC:23:3F:23:9C:79	Impact Drill	Impact Drill 1	10/31/2011 00:00 AM	12/31/2037 23:59 PM
F239C80	AC:23:3F:23:9C:80	GPS	BLE Enable GPS	10/31/2011 00:00 AM	12/31/2037 23:59 PM

Deactivate | Export | Upload .CSV File | Scan | Add | Update

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Assignment

Manger Name	Assigned Driver	Vehicle #	GPS ID	Make	GPS BLE Status	BLE Equipment Status
MCCONNEY, RICK	EVAN	10-00683	4562084459	CHEV	Assigned	5
MCCONNEY, RICK	ATHEY	10-00423	4562074456	CHEV	Assigned	6
MCCONNEY, RICK	ADAMS	10-00254	4562074456	FORD	Assigned	6
MCCONNEY, RICK	DUKE	10-00374	4562078849	FORD	Assigned	6

View / Update BLE Detail

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Beacon MAC ID / ESN

- Beacon MAC ID / ESN
- Vehicle #
- Current Driver
- Assigned Drive

AC:23:3F:23:7D:37

Time Sta Today

8:00 AM [Dashboard updates every 1 hour]

Refresh

Beacon stat

Vehicle ID		Reporting
10-00683		5
10-00423	5	6
10-00374	6	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
3	0

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count: 40

Reported Item Count: 40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: MAC ID / ESN: **AC:23:3F:23:7D:37**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes] Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – By Admin					

Map



Equipment Label : Long Ladder

Beacon Name: F237D37

MAC ID / ESN: AC:23:3F:23:7D:37

Description: Lorem ipsum

End Date/Time: 10/31/2011 00:00 AM

Start Date/Time : 12/31/2037 23:59 PM

Assigned to Vehicle: 10-00423

Last Reported Vehicle : **10-00254 at** 10/20/ 2017 **08:20 AM**

Location : Latitude: 31.732216 Longitude: -82.835083

Cancel | Notify Driver

Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

Initiate Scan | Notify Driver | Export Scan Report

5:49 PM 8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: MAC ID / ESN: **AC:23:3F:23:7D:37**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes] Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – By Admin					

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

Initiate Scan

Notify Driver

Export Scan Report

Message To : ATHEY; ADAMS

CC : MCCONNEY, RICK

ADAMS ,
The scan report identified you have **additional** following item(s)

1. Long Ladder
2. Impact Drill

Last Reported Vehicle : 10-00254 at 10/20/ 2017 08:20 AM
Location : Latitude: 31.732216 Longitude: -82.835083

The equipment(s) belong to **Vehicle # 10-00423** please pass it the current driver: ATHEY the and initiate BLE Scan of the devices

Thanks,
iLocate Support Team
1 (800) 333 HELP

Cancel | Send

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: MAC ID / ESN: **AC:23:3F:23:7D:37**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 08:20 AM	Success	-	7 of 5 !	ATHEY !
Automatic – By Admin	10/20/ 2017 08:10 AM	Success	-	7 of 5 !	ADAMS !

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By: Vehicle #

- Beacon MAC ID / ESN
- Vehicle #
- Current Driver
- Assigned Drive

10-00683

Time St: Today

8:00 AM [Dashboard updates every 1 hour]

Refresh

Beacon stat

Vehicle ID		Reporting
10-00683		5
10-00423	5	6
10-00374	6	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count:	40
Reported Item Count:	40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Vehicle: **10-00683**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00683	EVAN

Initiate Scan

BLE Scan Report History

Problem Summary: **None**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Automatic – By Admin	10/20/ 2017 6:20 PM	Success	-	5 of 5	EVAN
Manual - By Technician	10/20/ 2017 03:05 PM	Success	-	5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Success		5 of 5	EVAN
Automatic – By Admin	10/20/ 2017 02:35 PM	Success	-	5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	5 of 5	EVAN
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	5 of 5	EVAN
Automatic – End of Job	10/20/ 2017 11:30 AM	Success		5 of 5	EVAN
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	EVAN

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	95%	.8m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By: Assigned Drive

- Beacon MAC ID / ESN
- Vehicle #
- Current Driver
- Assigned Drive

ATHEY

Time St: Today

8:00 AM [Dashboard updates every 1 hour]

Refresh

Beacon stat

Vehicle ID		Reporting
10-00683		5
10-00423	5	6
10-00374	6	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count:	40
Reported Item Count:	40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

BLE Scan Details For: Assigned Driver: **ATHEY**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00423 !	ATHEY

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Automatic – Ignition ON	10/20/ 2017 02:50 PM	Failure	-	6 of 5 !	ADAMS !
Automatic – By Admin	10/20/ 2017 02:35 PM	In Progress	Bluetooth OFF	-	ADAMS
Automatic – Ignition ON	10/20/ 2017 02:15 PM	Success	-	6 of 5 !	ADAMS !
Manual - By Technician	10/20/ 2017 12:00 PM	Success	-	6 of 5 !	ADAMS !
Automatic – End of Job	10/20/ 2017 11:30 AM	Failure	Bluetooth OFF	-	ATHEY
Automatic – Ignition ON	10/20/ 2017 08:30 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 08:00 AM	Success	-	5 of 5	ATHEY
Manual - By Technician	10/20/ 2017 07:55 AM	Success	-	5 of 5	ATHEY

Notify Driver | Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	!	-	-
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	✓	26%	1m
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By Select... Search

Time St Today

8:00 AM [Dashboard updates every 1 hour] Refresh

Beacon status

Search By Vehicle ID

Vehicle ID	Assigned	Reporting
10-00683	5	5
10-00423	5	6
10-00374	6	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
2	1

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count: 40

Reported Item Count: 40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type All

Search

Refresh

All
Low Battery
System Reporting
Tech Reporting

Date & Time	Driver Nam		MAC ID / ESN	Message	Actioned On	Status
11/14/2017 08:20 AM	ATHEY		AC:23:3F:23:7D:36	The scan report identified the BLE is out of Battery	-	-
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	-	-
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:39	The scan report identified the BLE is out of Battery	-	-
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:42	The scan report identified the BLE is out of Battery	-	-
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:46	The scan report identified the BLE is out of Battery	-	-
11/13/2017 06:30 PM	EVAN	Tech Reporting	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	-	-
11/13/2017 05:45 PM	DUKE	System Reporting	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	11/13/2017 05:45 PM	Notified Driver
11/13/2017 09:30 AM	ADMAS	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/13/2017 09:30 AM	Ticket Raised

Delete | Raise Ticket | Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type Low Battery

Search

Refresh

Date & Time	Driver Name	Alert Type	MAC ID / ESN	Message	Actioned On	Status
11/14/2017 08:20 AM	ATHEY	Low Battery			-	-
11/14/2017 08:20 AM	ATHEY	Low Battery			-	-
11/14/2017 08:20 AM	ATHEY	Low Battery			-	-
11/14/2017 08:20 AM	ATHEY	Low Battery			-	-
11/14/2017 08:20 AM	ATHEY	Low Battery			-	-
11/13/2017 09:30 AM	ADMAS	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/13/2017 09:30 AM	Ticket Raised

Success

Ticket has been raised successfully for battery change for the selected BLEs

OK

Delete

Raise Ticket

Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type Low Battery

- All
- Low Battery
- System Reporting
- Tech Reporting

Search

Refresh

Date & Time	Driver Nam		MAC ID / ESN	Message	Actioned On	Status
11/14/2017 08:20 AM	ATHEY		AC:23:3F:23:7D:36	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:39	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:42	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:46	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/13/2017 09:30 AM	ADMAS	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/13/2017 09:30 AM	Ticket Raised

Delete | Raise Ticket | Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type Tech Reporting

Search

Refresh

	Date & Time	Driver Name	Alert Type	MAC ID / ESN	Message	Actioned On	Status
☑	11/13/2017 06:30 PM	EVAN	Tech Reporting	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	-	-

Delete

Raise Ticket

Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

BLE Scan Details For: MAC ID / ESN: **AC:23:3F:23:7D:37**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – By Admin					

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

Initiate Scan

Notify Driver

Export Scan Report

Equipment Label : Long Ladder

Beacon Name: F237D37

MAC ID / ESN: AC:23:3F:23:7D:37

Description: Lorem ipsum

End Date/Time: 10/31/2011 00:00 AM

Start Date/Time : 12/31/2037 23:59 PM

Assigned to Vehicle: 10-00423

Last Reported Vehicle : **10-00254 at** 10/20/ 2017 **08:20 AM**

Location : Latitude: 31.732216 Longitude: -82.835083

Cancel

Notify Driver

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

BLE Scan Details For: MAC ID / ESN: **AC:23:3F:23:7D:37**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

BLE Scan Report History

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician					
Automatic – By Admin					

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

Initiate Scan

Notify Driver

Export Scan Report

Message To : ATHEY; ADAMS

CC : MCCONNEY, RICK

ADAMS ,
The scan report identified you have **additional** following item(s)

1. Long Ladder
2. Impact Drill

Last Reported Vehicle : 10-00254 at 10/20/ 2017 08:20 AM
Location : Latitude: 31.732216 Longitude: -82.835083

The equipment(s) belong to **Vehicle # 10-00423** please pass it the current driver: ATHEY the and initiate BLE Scan of the devices

Thanks,
iLocate Support Team
1 (800) 333 HELP

Cancel

Send

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

BLE Scan Details For: MAC ID / ESN: **AC:23:3F:23:7D:37**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
10-00254	ADAMS

Initiate Scan

BLE Scan Report History

Problem Summary: **Additional Beacon ; Vehicle / Driver Assignment Mismatch**

Scan Type	Time	Status	Reason	Item Status	Active Driver
Manual - By Technician	10/20/ 2017 08:20 AM	Success	-	7 of 5	ATHEY
Automatic – By Admin	10/20/ 2017 08:10 AM	Success	-	7 of 5	ADAMS

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
GPS	✓	99%	1m
Impact Drill	✓	26%	1m
Little Giant Ladder	✓	63%	1.5 m
Long Ladder	!	-	-
Long Ladder	✓	99%	1m

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type Tech Reporting

Search

Refresh

- All
- Low Battery
- System Reporting
- Tech Reporting

Date & Time	Driver Nam	MAC ID / ESN	Message	Actioned On	Status
11/13/2017 06:30 PM	EVAN	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	11/14/2017 11:00 AM	Notified Driver

Delete | Raise Ticket | Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type All

Search

Search

Refresh

	Date & Time	Driver Name	Alert Type	MAC ID / ESN	Message	Actioned On	Status
	11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:36	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
	11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
	11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:39	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
	11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:42	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
	11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:46	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
	11/13/2017 06:30 PM	EVAN	Tech Reporting	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	11/14/2017 11:00 AM	Notified Driver
☑	11/13/2017 05:45 PM	DUKE	System Reporting	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	11/13/2017 05:45 PM	Notified Driver
☑	11/13/2017 09:30 AM	ADMAS	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/13/2017 09:30 AM	Ticket Raised

Delete

Raise Ticket

Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Notification Dashboard: Alert Type All

Search

Search

Refresh

Date & Time	Driver Name	Alert Type	MAC ID / ESN	Message	Actioned On	Status
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:36	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:38	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:39	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:42	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/14/2017 08:20 AM	ATHEY	Low Battery	AC:23:3F:23:7D:46	The scan report identified the BLE is out of Battery	11/14/2017 10:30 AM	Ticket Raised
11/13/2017 06:30 PM	EVAN	Tech Reporting	AC:23:3F:23:7D:37	The scan report identified that I have misplaced a item	11/14/2017 11:00 AM	Notified Driver

Delete

Raise Ticket

Search MAC ID / ESN

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification 6 | Admin | Help

Search By: Vehicle #

- Beacon MAC ID / ESN
- Vehicle #
- Current Driver
- Assigned Drive

ABCD!!!

Time St: Today

8:00 AM [Dashboard updates every 1 hour]

Refresh

Beacon stat

Vehicle ID		Reporting
10-00683		5
10-00423	5	6
10-00374	6	4
10-00254	5	7

BLE Status



BLE Enabled GPS: 1

BLE Disable GPS: 3

Assigned	Not Assigned
3	0

Problem Summary

Issues Reported	Vehicle Count
Additional Beacon	2
Beacon Missing	1
Driver Assignment Mismatch	2
Vehicle / Blue Truth Not Reporting	1

Scan Success Rate



Scan summary

Manual – By Technician	85%
Automatic – By Admin	62%
Automatic – Ignition ON	74%
Automatic – End of Job	28%

Equipment Reported Missing

Jan 01 – Jan 15



Item Availability Summary



Item Availability

Expected Item count:	40
Reported Item Count:	40

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

BLE Scan Details For: Vehicle: **ABCD111**

Time St Today

6:15 PM [Dashboard updates every 5 Minutes]

Refresh

Reporting Details

Vehicle #	Assigned Driver
No Records to Display	

Initiate Scan

BLE Scan Report History

Problem Summary: **No records to display**

Scan Type	Time	Status	Reason	Item Status	Active Driver
No Records to Display					

Notify Driver

Export Scan Report

Map



Equipment Details

Label	Scan Result	Battery	Distance
No Records to Display			

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

Search

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Search by ATTUID

- STEPHENSON, RANDALL [rs2982]
  - BLASE, WILLIAM [wb971w]
  - BREWER, CINDY A [cb7383]
  - THETFORD, TRAVIS [tt1741]
    - GULLETTE, TOM [tg1267]
      - HALPIN, ED [eh7[illegible]2h]
      - ARMAD FREEMAN [af3254]
      - Goldberg. A [ga9842]
      - Stephenson. R [sr4372]
    - POWERS, HEATH A [hp4721]
  - STEVENS, TIMOTHY W. [ts7156]
  - BEN TORTORICE [bt3232]

ffective Start Date	Effective End Date

Enable

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Search by ATT UID

Results for: POWERS, HEATH A [hp4721]

Back

Results for: ARMAD [af3254]

Vehicle Enablement Detail

Vehicle #	Enablement Status	Effective
10-00653	-	-
10-00788	-	-
10-00892	-	-
10-00990	-	-
10-00994	-	-

Define Dates

Effective Start Date: 01/01/2018

Effective End Date: 07/01/2018

Cancel

Submit

Block

Enable

5:49 PM
8/11/2016

File Edit View History Bookmarks Tools Help

VTS - Vehicle Tracking System

ilocate.com

iLocate

Welcome MCCONNEY, RICK

Dashboard | BLE Scan Report | BLE Assignment | Notification | Admin | Help

Search by ATT UID

Results for: **POWERS, HEATH A [hp4721]**

Back

Vehicle Enablement Detail

Vehicle #	Enablement Status	Effective Start Date	Effective End Date
10-00653	Enable	01/01/2018	07/01/2018
10-00788	Enable	01/01/2018	07/01/2018
10-00892	Enable	01/01/2018	07/01/2018
10-00990	Enable	01/01/2018	07/01/2018
10-00994	Enable	01/01/2018	07/01/2018

Block

Enable

5:49 PM
8/11/2016