

Home

[1/4] HOME

ROBOT OK

ROBOT PWR 82%

RC 4.08V RSSI -67dBm

MODE HOLD

CMD L+0.00 T+0.00

ACT L+0.00 T+0.00

Telemetry

[2/4] TELEMETRY

LINK OK STATUS 0x01

GPS 3D AGE 0s

LAT 29.643210

LON -82.354110

ALT 31.4m

RSSI -67dBm

Settings

[3/4] SETTINGS

> FREQ 915 MHz

BW 500 kHz

SF 7

DEAD 0.05

LOW L/T 0.5/0.5

HIGH L/T 1.5/1.5

Joystick Calibration

[4/4] CALIBRATION

MOVE FULL RANGE

X MIN 312 MAX 3786

Y MIN 298 MAX 3801

RELEASE TO CENTER

B2: FINISH