



Used mercury-containing UVC lamp — safe recycling workflow

1 Isolate and lock out




Both groups Off · verify
Disarm · disconnect · LOTO

2 Hold only the base



Do not twist, bend, or press
the glass tubes.

3 Package immediately




Original carton or rigid, closed,
cushioned lamp container.

4 Label the container



Add start date, model, quantity
and responsible work area.

5 Store dry and protected



Away from traffic, weather,
vehicles and new lamps.

6 Approved recycler




EHS confirms recycler, pickup,
transport and acceptance.

7 Record the transfer



Robot, position, hours, date,
container and recycler receipt.

8 If glass breaks



Cordon off; do not vacuum or
sweep; follow spill procedure.