THE WHEELER DEALERS
INDEPENDENT VEHICLE INSPECTION

Vehicle Inspection Report

2024 Nissan Sunny · Report No. WD-261025-D003
Prepared for SAMPLE ONLY - Not a real inspection

VEHICLE DETAILS	RECORDED INFORMATION
Make / model	Nissan Sunny
Model year / regional specification	2024 / GCC
VIN	3N1CN8AD3RL853607
Odometer	55,285 km; no indication of alteration observed
Fuel / engine / transmission	Petrol / 4-cylinder / Automatic
Exterior colour / vehicle type	Grey / Sedan
Keys / spare tyre	1 key / spare tyre available
Inspection date / time	20 August 2026 / 9:00 PM
Inspection location	Dubai, Dubai
Inspector	—
Inspection framework	134-parameter inspection; 134 recorded



Front three-quarter view (reference photo, demo only)

Purpose and reading guide

This report records observations by vehicle system. It does not certify the vehicle, grade overall quality, or recommend whether it should be purchased. The customer makes the purchasing decision. No pass/fail labels, overall score, pass percentage, or defect percentage are used.

Observation wording: “No obvious issue observed” records that nothing was found during this check and is not a guarantee that a component is fault-free; “Wear or damage observed” describes a finding, with details in the comment column; “Not assessed / unavailable” identifies an inspection limitation; “Not recorded” means no entry was made for that parameter.

01. Vehicle identification and general details

PARAMETER	OBSERVATION / RECORD
Make	Nissan
Model	Sunny
Model year	2024
Regional specifications	GCC
VIN / chassis number	3N1CN8AD3RL853607
Transmission type	Automatic
Engine configuration	4-cylinder
Odometer authenticity	No indication of alteration observed
Odometer reading	55,285 km
Fuel type	Petrol
Vehicle type	Sedan
Exterior colour	Grey
Spare tyre availability	Available
Number of keys	1

02. Tyres

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Front-left tyre (FL)	No obvious issue observed — DOT 23/2023 · Tread 5.2 mm	—
Front-right tyre (FR)	No obvious issue observed — DOT 23/2023 · Tread 5.2 mm	—
Rear-left tyre (RL)	No obvious issue observed — DOT 23/2023 · Tread 6.1 mm	—
Rear-right tyre (RR)	No obvious issue observed — DOT 23/2023 · Tread 6.1 mm	—
Spare tyre (ST)	No obvious issue observed — DOT 18/2023 · Tread 7.8 mm	—

03. Rims / wheels

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Front-left rim	Damaged or scratched	Kerb scuffing on outer lip, approx. 6 cm.
Front-right rim	No obvious issue observed	—
Rear-left rim	No obvious issue observed	—
Rear-right rim	No obvious issue observed	—
Spare wheel rim	Not assessed / unavailable	Spare wheel not removed from its well.

04. Braking system

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Front-left brake pads	No obvious issue observed	—
Front-left brake disc	Wear or damage observed	Surface scoring observed; disc requires polishing. 
Front-right brake pads	No obvious issue observed	—
Front-right brake disc	Wear or damage observed	Surface scoring observed; disc requires polishing.
Rear-left brake pads	No obvious issue observed	—
Rear-left brake disc	Wear or damage observed	Surface scoring observed; disc requires polishing.
Rear-right brake pads	No obvious issue observed	—
Rear-right brake disc	Wear or damage observed	Surface scoring observed; disc requires polishing.
Front-left brake disc surface	Wear or damage observed	Surface scoring observed; disc requires polishing.
Front-right brake disc surface	Wear or damage observed	Surface scoring observed; disc requires polishing.
Rear-left brake disc surface	Wear or damage observed	Surface scoring observed; disc requires polishing.
Rear-right brake disc surface	Wear or damage observed	Surface scoring observed; disc requires polishing.

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Front brake type	Disc	—
Rear brake type	Disc	—

05. Suspension

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Front suspension overall	No obvious issue observed	—
Front-right suspension	No obvious issue observed	—
Front-left suspension	No obvious issue observed	—
Rear suspension overall	No obvious issue observed	—
Rear-right suspension	No obvious issue observed	—
Rear-left suspension	No obvious issue observed	—
Front suspension surface damage	No obvious issue observed	—
Rear suspension surface damage	No obvious issue observed	—

06. Interior and exterior trim

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Roof lining	No obvious issue observed	—
Rear-view mirror	No obvious issue observed	—
Steering wheel upholstery	No obvious issue observed	—
Seats upholstery	No obvious issue observed	—
Gear lever	No obvious issue observed	—
Trunk lining	No obvious issue observed	—
Armrest and side pockets	No obvious issue observed	—
Dashboard	No obvious issue observed	—
Floor mats	No obvious issue observed	—
Doors	No obvious issue observed	—
Front windscreen	No obvious issue observed	—

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Rear windscreen	No obvious issue observed	—
Side windows	No obvious issue observed	—
Hood / bonnet	No obvious issue observed	—
Trunk	No obvious issue observed	—
Front bumper	No obvious issue observed	—
Rear bumper	No obvious issue observed	—

07. Electrical system and equipment

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Gear lever	No obvious issue observed	—
Doors	No obvious issue observed	—
Rear windscreen	No obvious issue observed	—
Steering	No obvious issue observed	—
Key	No obvious issue observed	—
Infotainment system	No obvious issue observed	—
Windows operation	No obvious issue observed	—
Seats adjustment	No obvious issue observed	—
Door lock	No obvious issue observed	—
A/C control and cooling	No obvious issue observed	—
Centre console buttons	No obvious issue observed	—
Cameras	No obvious issue observed	—
Gauges	No obvious issue observed	—
Rear-view / side mirrors	No obvious issue observed	—
A/C grilles	No obvious issue observed	—
Ignition system	No obvious issue observed	—
Brake lights	No obvious issue observed	—
Headlights	No obvious issue observed	—

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Fog lights	No obvious issue observed	—
Reverse lights	No obvious issue observed	—
Number plate lights	No obvious issue observed	—
Indicators and hazard lights	No obvious issue observed	—
Wipers	No obvious issue observed	—
Soft-closing doors	Not assessed / unavailable	Not fitted to this vehicle.
Sunroof / moonroof	Not assessed / unavailable	Not fitted to this vehicle.
Interior lights	No obvious issue observed	—
Cruise control	No obvious issue observed	—
Horn	No obvious issue observed	—
Parking sensors	No obvious issue observed	—

08. Body and paint

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Front bumper	Original paint — 109 µm	—
Bonnet	Original paint — 113 µm	—
Front right fender	Original paint — 117 µm	—
Front left fender	Original paint — 121 µm	—
Front right door	Original paint — 125 µm	—
Front left door	Repainted — 310 µm	Thickness reading above surrounding panels.
Rear right door	Original paint — 105 µm	—
Rear left door	Original paint — 109 µm	—
Rear right fender	Original paint — 113 µm	—
Rear left fender	Original paint — 117 µm	—
Boot lid / tailgate	Original paint — 121 µm	—
Rear bumper	Original paint — 125 µm	—
Roof	Original paint — 129 µm	—

09. Engine

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Engine upper cover	No obvious issue observed	—
Engine shield cover	No obvious issue observed	—
Engine mounts	No obvious issue observed	—
Bonnet hinge and holder	No obvious issue observed	—
Turbo / supercharger	Not assessed / unavailable	Not fitted to this vehicle.
Fender liners	No obvious issue observed	—
Drive belt / pulleys	No obvious issue observed	—
Engine idle	No obvious issue observed	—
Engine oil filler cap	No obvious issue observed	—
Radiator	No obvious issue observed	—
Engine oil leaks	No obvious issue observed	—
Engine oil condition	No obvious issue observed	—
Coolant condition	No obvious issue observed	—
Coolant cap	No obvious issue observed	—
Hoses and pipes	No obvious issue observed	—
Exhaust system	No obvious issue observed	—
Four-wheel drive (4WD)	Not assessed / unavailable	Not fitted to this vehicle.

10. Transmission and drivetrain

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Transmission fluid level and condition	No obvious issue observed	—
Transmission fluid leaks	No obvious issue observed	—
Gear selector	No obvious issue observed	—
Unusual noise	No obvious issue observed	—
Gear shifting	No obvious issue observed	—
Differential	No obvious issue observed	—

11. Chassis and subframe

PARAMETER	OBSERVATION / RECORD	COMMENT / OBSERVATIONS
Core support	No obvious issue observed	—
Frame rail	No obvious issue observed	—
Wheel house	No obvious issue observed	—
Right fender apron	No obvious issue observed	—
Shock tower / shock mount	No obvious issue observed	—
Radiator side support (side baffle)	No obvious issue observed	—
Left fender apron	No obvious issue observed	—
Front body hinge pillar	No obvious issue observed	—
Front floor board	No obvious issue observed	—
Left door sill	No obvious issue observed	—
Centre pillar post (B-pillar)	No obvious issue observed	—
Mid floor board	No obvious issue observed	—
Body quarter panel	No obvious issue observed	—
C-pillar	No obvious issue observed	—
Seat frame	No obvious issue observed	—
Rear floor panel	No obvious issue observed	—
Left A-pillar	No obvious issue observed	—
Roof panel	No obvious issue observed	—
Right door sill	No obvious issue observed	—
Right A-pillar	No obvious issue observed	—

12. Diagnostic scan and inspector comments

PARAMETER	OBSERVATION / RECORD
Diagnostic scan history	One stored fault code found during the diagnostic scan (module and code not retrieved by the scan tool used).
Additional observations	All four brake discs show surface scoring and require polishing; see braking-system photographs. DEMONSTRATION ONLY — sample data.

PARAMETER	OBSERVATION / RECORD
Inspection limitations	Spare wheel rim not assessed: spare tyre could not be removed from its well without tools.

13. Photographic evidence and attachments

EXTERIOR OVERVIEW — 2 photos



Front three-quarter view (reference photo, demo only)



Rear view (reference photo, demo only)

INTERIOR OVERVIEW — 1 photo



Interior overview (reference photo, demo only)

SPECIFIC OBSERVATION — FRONT-LEFT BRAKE DISC — 1 photo



Front-left brake disc — surface scoring (reference photo, demo only)

14. Scope, limitations and customer decision

This report is a record of observations made during the inspection at the stated time. A visual, non-invasive inspection may not identify concealed, intermittent or future faults. Where access or test conditions limited the assessment, the limitation is stated in the report.

The report does not certify that the vehicle is safe, fault-free, mechanically sound, approved or suitable for purchase. No finding should be interpreted as a guarantee. The customer is responsible for reviewing the information and making their own purchasing decision.

> **THE WHEELER DEALERS**
>
> We document the facts. The customer makes the decision.
>
> www.thewheelerdealers.com · info@thewheelerdealers.com · Report No. WD-261025-D003