
A Target clearance was not realized
Actual cup-bottom / support gap [mm]
origin 0 m
origin 14 m
commanded clearance
Native time relative to opening command [s]
B Motion failures remain at contact
Max |joint acceleration| [rad/s²]
origin 0 m
origin 14 m
local motion gate
Native time relative to opening command [s]