
NA1: one native asynchronous P0 loop (wiring check, not task success)
APPLIED at original tick
REJECTED (outside joint limits)
STALE (tick passed before return)
A Worker intervals and slot outcomes on the native physics tick axis
start→return
APPLIED
REJECTED
STALE slot
B Measured joint position and the target held between applied commands
joint position (rad)
fr3_joint1 measured
fr3_joint1 stepped target
fr3_joint4 measured
fr3_joint4 stepped target
native physics tick since task origin (dt = 0.0042 s)