

Department of Geology and Environmental Geosciences DeKalb, Illinois 60115-2828 815-753-7937 FAX 815-753-1945 www.niu.edu/geology

September 6, 2012

To Whom It May Concern:

On August 24, 2012, water was sampled from the community drinking water well in Correlejo. The water was analyzed on-site for temperature, pH, electric conductivity, and turbidity. Additional water was collected aseptically for presence/absence of coliform bacteria and analyzed within 24 hours of collection. The analysis for fluoride, sulfate, and nitrate were done using an ion chromatograph (IC) while the sample for arsenic were analyzed using inductively coupled plasma mass spectrometry (ICP-MS) at Northern Illinois University. Below is a table with the final results.

	units	NOM*	Correlejo
Fluoride	mg/L	1.5	0.88
Sulfate	mg/L	400	6.33
Nitrate	mg/L	45	23.49
Arsenic	$\mu g/L$	25	3.4
Temperature	°C	N/A	24.8
рН		6.5-8.5	8.01
Electric Conductivity***	$\mu S/cm$	0-800	261
Turbidity	NTU	5	0
Total Coliform **	+/-	2CFU/ml	Negative

^{*}NOM= Mexican standard NOM-127-ssa1-1994

The results indicate that all results are within normal range.

If you have any questions or comments, feel free to contact me at the above address.

Melissa Lenczewski Lenczewski@niu.edu

Melisse Lengual

^{**} Coliform was a presence/absence test and could not quantify the organisms

^{***} Recommended levels for fresh water



Allende #5, Colonia Insurgentes San Miguel de Allende, Guanajuato, Mexico 37712

T: (+52) 415-154-8091 info@caminosdeagua.org www.caminosdeagua.org

A quien corresponda,

El 24 de agosto de 2012 se tomaron muestras de agua destinada al consumo humano en la comunidad de **Correlejos**. La temperatura, el pH y la turbidez del agua fueron analizadas en sitio. Muestras adicionales de agua fueron tomadas de forma aséptica para el análisis de la presencia de bacterias coliformes; dicho análisis tuvo lugar en las 24 horas siguientes a la toma de la muestras.

El análisis de aniones fue realizado con la ayuda de un cromatógrafo de iones (IC); el análisis de la presencia de metales fue realizado utilizando un espectrómetro de masas por plasma de acoplamiento inductivo (ICP-MS). Ambos análisis se llevaron a cabo en los laboratorios de la Northern Illinois University. En la siguiente tabla se indican los resultados obtenidos.

	Unidades	NOM*	Correlejos
pН		6.5-8.5	8.01
Arsénico**	mg/L	0.01 (0.025)	0.003
Fluoruro	mg/L	1.5	0.08
Cloruro	mg/L	250	26.97
Sulfato	mg/L	400	6.33
Nitrato	mg/L	45	23.49
Coliformes Totales	MPN/100mL	0	negativo
Turbidez		5	0
Temperatura		-	24.8

^{*}NOM = Mexican NOM, NOM-127-ssal-1994

Conclusiones

Los resultados indican que las concentraciones de fluoruros y arsénico en el agua obtenida del pozo no exceden los valores recomendados en la normativa mexicana de agua potable.

Atentamente,

Dylan Terrell

Caminos de Agua, Director Ejecutivo

^{**} Caminos de Agua sigue las normas y recomendaciones de la Organización Mundial de la Salud (OMS) en nuestras recomendaciones, dadas las consecuencias graves para la salud del exceso de arsénico. Normas de la OMS para el arsénico en el agua potable es de 10 μg/L (0.01 mg/L).