



Testing of 8 production cards

Raman Khurana, B. Gomber, S. Mukherjee, D. Roy, M. Sharan SINP Kolkata, INDIA

(11th April 2014)

Status of testing at SINP

- 8 μHTR cards v1.3 assembled in India.
 - used machine assembly now.
- Testing of cards is ongoing at SINP.
 - Firmare used for Front FPGA = 00.0b.20
 - Firmare used for Back FPGA = 00.0d.40
- Following tests are performed :
 - I2C communication(with small issue initially with 2 cards) working fine.
 - For PPODs
 - IBER Test @ 4.8 Gbps and 6.4 Gbps using μTCA crate.
 - Worked fine in 7 cards
 - Random behaviour in 1 card: Ibert console not coming
 - Front Link works upto 6.4 Gbps

Resistance Problem


- 2 cards were not showing correct I2C information for 1V PM.
- Card 106 Resistance near C402 was dry soldered (33 Kohm)
- Card 104 Resistance near C503 was dry soldered (33 Kohm)
- These resistors were connected with 1V PM.
- After doing the soldering properly, I2c communation was working fine.
- Next Steps :
 - SFPs and front-back link testing.




I2C communication

```
pm 1VA -- 00:1e:c0:80:e4:38 (S/N = 1015)
   Id-Version = 1 Mezz Type = 1 / 1 (PM1.0)
   Tested 7-2-2014 at 'SINP-INDIA' by 'Raman' using release 1.0.2
 pm 1VB -- 00:1e:c0:81:6f:af (S/N = 1006)
   Id-Version = 1 Mezz Type = 1/1 (PM1.0)
   Tested 15-1-2014 at 'SINP-INDIA' by 'Debarati' using release 1.0.2
 pm 3 3V - 00:1e:c0:80:fa:7e (S/N = 1006)
   Id-Version = 1 Mezz Type = 1/3 (PM3.3)
   Tested 3-2-2014 at 'SINP-INDIA' by 'Debarati' using release 1.0.2
 apm 1 8V -- 00:04:a3:a5:f8:7a (S/N = 1009)
   Id-Version = 1 Mezz Type = 2 / 1 (APM1.8)
   Tested 28-1-2014 at 'SINP-INDIA' by 'Bhawna' using release 1.0.2
Layer 1: asked for 8, found 8
 apm 2 5V - 00:1e:c0:81:01:c3 (S/N = 1003)
   Id-Version = 1 Mezz Type = 2 / 1 (APM1.8)
   Tested 3-2-2014 at 'SINP-INDIA' by 'Debarati' using release 1.0.2
 cpld_mezz -- 00:04:a3:8f:15:46 (S/N = 65535)
   Invalid ID block observed
```

IBER Test 6.4 Gbps :: PPODs



IBER Test 4.8 Gbps :: Error for 1 card



Summary

- 8 μHTR cards v1.3 assembled in India.
- Preliminary testing at SINP shows good results.
- I2C communication passed for all mezzanines.
- IBER Test using crate worked for 7 production cards.
- IBER Test randomly working with 1 card (104)

Comments & Suggestions

Backup

I2C communication

```
back FPGA (sysmon) -- 0.98 V 2.53 V 47.0 degC
 front FPGA (sysmon) -- 0.99 V 2.52 V 46.8 degC
 pm_1VA -- 1.01 V 40.9 degC
pm_1VB -- 1.01 V 38.9 degC
pm_3_3V -- 3.35 V 37.6 degC
apm_1_8V -- 1.62 V 45.8 degC
Layer 1: asked for 8, found 8
 apm_2_5V -- 2.53 V 53.0 degC
 ppod rx0 -- 2.51 V 3.27 V 28.6 degC
Layer 1: asked for 8, found e8
 ppod_rx1 -- 2.51 V 3.28 V 26.5 degC
 ppod tx -- 2.43 V 3.23 V 39.2 degC
```

µHTR cards testing status @ SINP