
5Ghoul Framework 5G NR Attacks and 5G OTA Fuzzing


Matheus E. Garbelini Sudipta Chattopadhyay

Joint work with Zewen Shang, Sumei Sun, Ernest Kurniawan






Motivation - What can fail?



Motivation – Where it can fail? Complexity and too many choices

Attack surfaces on wireless firmware

General Device Firmware Layout










<u>Critical</u>. all wireless devices affected.


Introduction - Over-the-Air (OTA) Fuzzing for 5G

How to find issues in complex and closed-source protocol stacks?



Introduction - Over-the-Air (OTA) Fuzzing for 5G


How to find issues in complex and closed-source protocol stacks?




Introduction - Over-the-Air (OTA) Fuzzing for 5G

How to find issues in complex and closed-source protocol stacks?


5G Base Station (gNB) / 5G OTA Fuzzer



- 1. Man-in-the-Middle (MitM) based approach
- 2. Control of downlink before radio transmission





5Ghoul Framework Overview - Requirements



5Ghoul Framework Overview – Hardware Setup










Over-the-Air (OTA) Fuzzing for 5G







Fuzzing Demo!










5Ghoul Attacks


How can we launch attacks with this?

5G OTA Fuzzer / Rogue Base Station




Attack Model

Adversarial or Malicious gNB



5Ghoul Attacks

Attack Demo!



5Ghoul Attacks – Summary of Findings


V1 - Invalid PUSCH Resource Allocation OAI UE RRC DoS Pending V2 - Empty RRC dedicatedNAS-Message OAI UE RRC, NAS DoS Pending V3 - Invalid RRC Setup Fibocom FM150-AE RRC DoS Patched V4 - Invalid RRC Reconfiguration Simcom SIM8202G MAC, RRC DoS Patched Telit FT980m Telit FT980m MAC, RLC DoS CVF-2023-33043 (7.2) V6 - NAS Unknown PDU Fibocom FM150-AE NAS DoS CVF-2023-33044 Asus ROG Phone 5s Telit FT980m Asus ROG Phone 5s NAS DoS CVF-2023-33044 Asus ROG Phone 5s Telit FT980m Asus ROG Phone 5s RRC Hang/Downgrade CVF-2023-33042 (7.2) V7 - Disabling 5G / Downgrade via RRC Simcom SIM8202G RRC Hang/Downgrade CVF-2023-33042 (7.2) V8 - Invalid RRC Setup spCellConfig OnePlus Nord CE 2 5G RRC DoS CVF-2023-33042 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G RRC DoS CVF-2023-32844 (7.6) V10 - Invalid RRC Data Sequence	Implementation Vulnerability	Affected Modems/Smartphones	Protocols	Impact	CVE Status
V3 - Invalid RRC Setup	V1 - Invalid PUSCH Resource Allocation	OAI UE	RRC	DoS	Pending
Simcom SIM8202G Simcom SIM8202G MAC, RRC DoS Patched	V2 - Empty RRC dedicatedNAS-Message	OAI UE	RRC, NAS	DoS	Pending
V4 - Invalid RRC Reconfiguration Simcom SIM8202G MAC, RRC DoS Patched (7.1) V5 - Invalid MAC/RLC PDU Telit FT980m MAC, RLC DoS CVE-2023-33043 (7.2) V6 - NAS Unknown PDU Fibocom FM150-AE ASUB ROG Phone 5s NAS DoS CVE-2023-33044 (7.3) V7 - Disabling 5G / Downgrade via RRC Simcom SIM8202G RRC Hang/Downgrade CVE-2023-33042 (7.3) V8 - Invalid RRC Setup spcEllConfig OnePlus Nord CE 2 5G RRC DoS CVE-2023-33042 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G RRC DoS CVE-2023-32842 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G RLC DoS CVE-2023-32844 (7.6) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G RLC DoS CVE-2023-32846 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2023-32846 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2023-32846 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2023-32841 Xiaomi	V3 - Invalid RRC Setup	Fibocom FM150-AE	RRC	DoS	Patched
Telit FT980m Simcom SIM8202G Asus ROG Phone 5s Telit FT980m Fibocom FM150-AE Asus ROG Phone 5s Telit FT980m Fibocom FM150-AE Asus ROG Phone 5s Telit FT980m Fibocom FM150-AE Asus ROG Phone 5s Telit FT980m Asus ROG Phone 5s Simcom SIM8202G Fibocom FM150-AE Quectel RM500Q-GL Quectel RM500Q-GL Quectel RM500Q-GL Telit RC		Simcom SIM8202G			
(7.1) V5 - Invalid MAC/RLC PDU	V4 - Invalid RRC Reconfiguration	Simcom SIM8202G	MAC, RRC	DoS	Patched
Asus ROG Phone 5s Tellt FT980m Fibocom FM150-AE Asus ROG Phone 5s Tellt FT980m Fibocom FM150-AE Asus ROG Phone 5s Tellt FT980m Tellt FT980		Telit FT980m			
Telit FT980m	(7.1) V5 - Invalid MAC/RLC PDU	Simcom SIM8202G	MAC, RLC	DoS	CVE-2023-33043
(7.2) V6 - NAS Unknown PDU Fibocom FM150-AE Asus ROG Phone 5s Tellt FT980m Asus ROG Phone 5s Tellt FT980m Asus ROG Phone 5s Simcom SIM8202G Fibocom FM150-AE Quectel RM500Q-GL (7.4) V8 - Invalid RRC Setup spCellConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40		Asus ROG Phone 5s			
Asus ROG Phone 5s Telit FT980m Asus ROG Phone 5s Telit FT980m Asus ROG Phone 5s Simcom SIM8202G Fibocom FM150-AE Quectel RM500Q-GL Quectel RM500Q-GL Quectel RM500Q-GL Tiabling RRC Setup spCellConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 Quectel RRC Dos CVE-2023-32842 Xiaomi Redmi K40 Quectel RRC Dos CVE-2023-32844 Xiaomi Redmi K40 Quectel RRC Dos CVE-2023-32846 Xiaomi Redmi K40 Quectel RRC Dos CVE-2023-32845 Xi		Telit FT980m			
Telit FT980m Asus ROG Phone 5s Simcom SIM8202G Fibocom FM150-AE Quectel RM500Q-GL Qu	(7.2) V6 - NAS Unknown PDU	Fibocom FM150-AE	NAS	DoS	CVE-2023-33044
Asus ROG Phone 5s Simcom SIM8202G Fibocom FM150-AE Quectel RM500Q-GL (7.4) V8 - Invalid RRC Setup spCellConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.6) V10 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xia		Asus ROG Phone 5s			
(7.3) V7 - Disabling 5G / Downgrade via RRCSimcom SIM8202G Fibocom FM150-AE Quectel RM500Q-GLRRCHang/DowngradeCVE-2023-33042(7.4) V8 - Invalid RRC Setup spCellConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32842(7.5) V9 - Invalid RRC pucch CSIReportConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32844(7.6) V10 - Invalid RLC Data SequenceOnePlus Nord CE 2 5G Xiaomi Redmi K40RLCDoSCVE-2023-20702(7.7) V11 - Truncated RRC physicalCellGroupConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32846(7.8) V12 - Invalid RRC searchSpacesToAddModListOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32841(7.9) V13 - Invalid RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32843(7.10) V14 - Null RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32845(7.11) V15 - Invalid RRC CellGroup IDOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32845(7.12) V16 - Invalid RRC CellGroupConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2024-20003		Telit FT980m			
Fibocom FM150-AE Quectel RM500Q-GL (7.4) V8 - Invalid RRC Setup spCellConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 One		Asus ROG Phone 5s			
Quectel RM500Q-GL (7.4) V8 - Invalid RRC Setup spCellConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40	(7.3) V7 - Disabling 5G / Downgrade via RRC	Simcom SIM8202G	RRC	Hang/Downgrade	CVE-2023-33042
(7.4) V8 - Invalid RRC Setup spCellConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40		Fibocom FM150-AE			
Xiaomi Redmi K40 (7.5) V9 - Invalid RRC pucch CSIReportConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redm		Quectel RM500Q-GL			
(7.5) V9 - Invalid RRC pucch CSIReportConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32844(7.6) V10 - Invalid RLC Data SequenceOnePlus Nord CE 2 5G Xiaomi Redmi K40RLCDoSCVE-2023-20702(7.7) V11 - Truncated RRC physicalCellGroupConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32846(7.8) V12 - Invalid RRC searchSpacesToAddModListOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32841(7.9) V13 - Invalid RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32843(7.10) V14 - Null RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32845(7.11) V15 - Invalid RRC CellGroup IDOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2024-20003(7.12) V16 - Invalid RRC CellGroupConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2024-20004	(7.4) V8 - Invalid RRC Setup spCellConfig	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2023-32842
Xiaomi Redmi K40 (7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC DoS CVE-2023-32845 CVE-2023-32845 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2023-32845 CVE-2024-20003		Xiaomi Redmi K40			
(7.6) V10 - Invalid RLC Data Sequence OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC Dos CVE-2023-32845 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC Dos CVE-2024-20003 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC Dos CVE-2024-20003	(7.5) V9 - Invalid RRC pucch CSIReportConfig	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2023-32844
Xiaomi Redmi K40 (7.7) V11 - Truncated RRC physicalCellGroupConfig OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList Niaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40		Xiaomi Redmi K40			
(7.7) V11 - Truncated RRC physicalCellGroupConfigOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32846(7.8) V12 - Invalid RRC searchSpacesToAddModListOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32841(7.9) V13 - Invalid RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32843(7.10) V14 - Null RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32845(7.11) V15 - Invalid RRC CellGroup IDOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2024-20003(7.12) V16 - Invalid RRC CellGroupConfigOnePlus Nord CE 2 5GRRCDoSCVE-2024-20004	(7.6) V10 - Invalid RLC Data Sequence	OnePlus Nord CE 2 5G	RLC	DoS	CVE-2023-20702
Xiaomi Redmi K40 (7.8) V12 - Invalid RRC searchSpacesToAddModList OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2023-32845 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2024-20003 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC DoS CVE-2024-20003		Xiaomi Redmi K40			
(7.8) V12 - Invalid RRC searchSpacesToAddModListOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32841(7.9) V13 - Invalid RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32843(7.10) V14 - Null RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32845(7.11) V15 - Invalid RRC CellGroup IDOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2024-20003(7.12) V16 - Invalid RRC CellGroupConfigOnePlus Nord CE 2 5GRRCDoSCVE-2024-20004	(7.7) V11 - Truncated RRC physicalCellGroupConfig	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2023-32846
Xiaomi Redmi K40 (7.9) V13 - Invalid RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC Dos CVE-2023-32845 Xiaomi Redmi K40 OnePlus Nord CE 2 5G RRC Dos CVE-2024-20003 Xiaomi Redmi K40 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC Dos CVE-2024-20004		Xiaomi Redmi K40			
(7.9) V13 - Invalid RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32843(7.10) V14 - Null RRC Uplink Config ElementOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2023-32845(7.11) V15 - Invalid RRC CellGroup IDOnePlus Nord CE 2 5G Xiaomi Redmi K40RRCDoSCVE-2024-20003(7.12) V16 - Invalid RRC CellGroupConfigOnePlus Nord CE 2 5GRRCDoSCVE-2024-20004	(7.8) V12 - Invalid RRC searchSpacesToAddModList	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2023-32841
Xiaomi Redmi K40 (7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G RRC DoS CVE-2023-32845		Xiaomi Redmi K40			
(7.10) V14 - Null RRC Uplink Config Element OnePlus Nord CE 2 5G RRC DoS CVE-2023-32845 Xiaomi Redmi K40 Xiaomi Redmi K40 RRC DoS CVE-2024-20003 Xiaomi Redmi K40 Xiaomi Redmi K40 RRC DoS CVE-2024-20004 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC DoS CVE-2024-20004	(7.9) V13 - Invalid RRC Uplink Config Element	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2023-32843
Xiaomi Redmi K40 (7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G RRC DoS CVE-2024-20003 Xiaomi Redmi K40 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC DoS CVE-2024-20004		Xiaomi Redmi K40			
(7.11) V15 - Invalid RRC CellGroup ID OnePlus Nord CE 2 5G Xiaomi Redmi K40 RRC DoS CVE-2024-20003 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC DoS CVE-2024-20004	(7.10) V14 - Null RRC Uplink Config Element	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2023-32845
Xiaomi Redmi K40 (7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC DoS CVE-2024-20004		Xiaomi Redmi K40			
(7.12) V16 - Invalid RRC CellGroupConfig OnePlus Nord CE 2 5G RRC DoS CVE-2024-20004	(7.11) V15 - Invalid RRC CellGroup ID	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2024-20003
		Xiaomi Redmi K40			
	(7.12) V16 - Invalid RRC CellGroupConfig	OnePlus Nord CE 2 5G	RRC	DoS	CVE-2024-20004
		Xiaomi Redmi K40			




- Seven (7) high severity
- 36,000 USD bug bounty
- Featured in Channel News Asia



5Ghoul Exploit Code (PoC) Generation - Overview








5Ghoul Exploit Code (PoC) Generation - Workflow







Thank you

Questions?

