HARDWARE DIAGNOSTIC REPORT
Lab: Precision Circuit Diagnostics
Date of Test: 2024-03-22
Item: OmniLaptop Pro 15
Serial Number: OMNI-LP-581102
Diagnosis: Corrosion on the motherboard from liquid ingress. Water damage confirmed under the keyl
Estimated Cost: $540.00