

# **Release Notes**

# **SMART-PROXY v2.08**

May 2018

### Introduction

This document provides firmware update information for: SMART-PROXY devices.

## **Support**

For more information on latest software releases, upgrade procedures, support, contact with your distributor and/or partner or visit www.astozi.com and/or email to support@astozi.com.

## **Update procedure**

Software version 2.08 brings improvements, improvements and new features. You are requested to thoroughly familiarize with the software update procedure.

#### WARNING !!!

After the software update is done, in most cases, it is necessary to clear the browser cache where the device configuration was performed.

## Assignments of devices models to firmware version:

Device model: Filename:

SMART-PROXY-ETH-POE SMART-PROXY-ETH-POE\_FW\_ALL.BIN

## **Update**

To update firmware of the device, please do the following steps:

- 1. Extract the file with the .BIN extension to a temporary directory.
- 2. Select the uncompressed file using the "Choose file" option in the firmware section of the Manage -> Maintenance menu.
- 3. Start the update procedure by pressing the green arrow button.
- 4. The update lasts for about 5 minutes.
- 5. After the update procedure is complete, the device will automatically restart.

Phone: +48 68 88 80 107 email: astozi@astozi.pl Fax: +48 68 88 80 117 web: www.astozi.pl

page: 2 z 5

## New functionality / improvements

This section shows the major improvements in each software release.

#### Version 2.08

no new functionality

#### Version 2.07

no new functionality

#### Version 2.06

no new functionality

#### Version 2.05

- · system management module
  - changes in the prefix of the device which is sent to the DHCP server from mote\_\_ to proxy\_

#### Version 2.04

- system management module
  - if you select "Reset to defaults with network settings" from the panel or press the reset button on your device, the IP address will be obtained from DHCP server and in case of failure the default address is 192.168.0.50
  - o the option "Reset to defaults" sets the installer mode ("installer mode") to ON. Communication with the gateway is possible by switching the installer mode to OFF in the Manage -> Configuration menu

#### Version 2.03

no new functionality

#### Version 2.02

- system management module
  - o added ability to configure TCP port to connect to systemONE server

#### Version 2.01

no new functionality

#### Version 2.00

- system management module
  - added the Failover IP option if the DHCP server does not work, the device uses the last saved static IP address
  - o added configuration restore options
- visualization module
  - o added display of measured data

#### Version 1.12

no new functionality

#### Version 1.11

no new functionality

astozi

ul. Inżynierska 8 67-100 Nowa Sól Poland

Phone: +48 68 88 80 107 Fax: +48 68 88 80 117

email: astozi@astozi.pl web: www.astozi.pl

page: 3 z 5

## **Version 1.10**

- visualization module
  - o added signal strength visualization

astozi

ul. Inżynierska 8 67-100 Nowa Sól Poland

Phone: +48 68 88 80 107 Fax: +48 68 88 80 117 email: astozi@astozi.pl web: www.astozi.pl

page: 4 z 5

## **Bug fixes**

This section shows the most important bug fixes in each version of the firmware.

### Version 2.08

- fixes in IE browser compatibility
- fixes in communication with systemONE

#### Version 2.07

• critical fix for using DHCP failover

#### Version 2.06

- critical fix to handle communication with the systemONE server
- fixes in saving information to logs

#### Version 2.05

increasing the waiting time to retrieve an address from the DHCP server from 5 to 30 seconds

#### Version 2.04

no fixes

#### Version 2.03

• critical fix to configuration of TCP port for connection to systemONE server

#### Version 2.02

no fixes

#### Version 2.01

• fixes in NTP support

#### Version 2.00

minor fixes in the web interface

#### Version 1.12

fixes in signal strength display module

#### Version 1.11

- DNS queries fixes
- minor fixes in the web interface

#### Version 1.10

• minor fixes in the web interface

astozi

ul. Inżynierska 8 67-100 Nowa Sól Poland

Phone: +48 68 88 80 107 Fax: +48 68 88 80 117

email: astozi@astozi.pl web: www.astozi.pl

page: 5 z 5