

Release Notes

SMART-PROXY v2.03

July 2017

SMART-PROXY

Introduction

This document provides firmware update information for: SMART-PROXY devices.

Support

For more information on latest software releases, upgrade procedures, support, contact with your distributor and/or partner or visit www.astozi.com and/or email to support@astozi.com.

Update procedure

Software version 2.03 brings improvements, improvements and new features. You are requested to thoroughly familiarize with the software update procedure.

WARNING !!!

After the software update is done, in most cases, it is necessary to clear the browser cache where the device configuration was performed.

Assignments of devices models to firmware version:

Device model: Filename:

SMART-PROXY-ETH-POE SMART-PROXY-ETH-POE FW ALL.BIN

Update

To update firmware of the device, please do the following steps:

- 1. Extract the file with the .BIN extension to a temporary directory.
- Select the uncompressed file using the "Choose file" option in the firmware section of the Manage -> 2. Maintenance menu.
- 3. Start the update procedure by pressing the green arrow button.
- 4. The update lasts for about 5 minutes.
- 5. After the update procedure is complete, the device will automatically restart.

Phone: +48 68 88 80 107 email: astozi@astozi.pl Fax: +48 68 88 80 117 web: www.astozi.pl

page: 2 z 4

SMART-PROXY

New functionality / improvements

This section shows the major improvements in each software release.

Version 2.03

no new functionality

Version 2.02

- system management module
 - o added ability to configure TCP port to connect to systemONE server

Version 2.01

no new functionality

Version 2.00

- system management module
 - o added the Failover IP option if the DHCP server does not work, the device uses the last saved static IP address
 - o added configuration restore options
- visualization module
 - o added display of measured data

Version 1.12

no new functionality

Version 1.11

no new functionality

Version 1.10

- visualization module
 - o added signal strength visualization

astozi

ul. Inżynierska 8 67-100 Nowa Sól Poland

Phone: +48 68 88 80 107 Fax: +48 68 88 80 117 email: astozi@astozi.pl web: www.astozi.pl

page: 3 z 4

SMART-PROXY

Bug fixes

This section shows the most important bug fixes in each version of the firmware.

Version 2.03

• critical fix to configuration of TCP port for connection to systemONE server

Version 2.02

no fixes

Version 2.01

• fixes in NTP support

Version 2.00

• minor fixes in the web interface

Version 1.12

• fixes in signal strength display module

Version 1.11

- DNS queries fixes
- minor fixes in the web interface

Version 1.10

minor fixes in the web interface

astozi

ul. Inżynierska 8 67-100 Nowa Sól Phone: +48 68 88 80 107 Poland Fax: +48 68 88 80 117

email: astozi@astozi.pl web: www.astozi.pl

page: 4 z 4