

MES Work Order SOP

Step 1: verify the work order id.

Step 2: investigate the anomaly cause.

Step 3: admin confirms and archives.