

Special circling procedures for RWY 24

MISSED APCH: Turn left/right (to avoid terrain) direct to GRASS.

Resume as depicted (follow the 11-1/19-1 proced. after GRASS).

Follow the chart Instrumental approach RWY 06 (chart 11-1 and 19-1). Upon reaching AR006 (D2.8 LCK for NON-RNAV users), turn left 034°, fly that heading until D1.78 LCK, turn right 064°, at D0.63 LCK, turn right, final RWY 24, resume descend via PAPI.



