

INSPECTION REPORT

North Village Extension and Stockpile

WEEKLY

Overall Status



Overall: CORRECTIVE ACTION REQUIRED

Project Information

Project:	North Village Extension and Stockpile
Location:	1036 Swift Ct, Vacaville, CA 95688, USA
WDID#:	N/A
Inspector:	Dan Baumbach
Date:	12/2/2025
QSP:	Dan Baumbach

Summary

Looks pretty good today, need to dump the concrete washout

Recommendations

No recommendations provided.

Certification and Signature

No signature provided

NOAA WEATHER REPORT

72-Hour Forecast

Weather Summary

MAX POP
(72H)
0%

TOTAL QPF
(72H)
0 in

Weather Station: Vacaville Nut Tree Airport




Rain Gauge at inspection


72-Hour Forecast Details

TUE 12/2, 10 AM	TUE 12/2, 1 PM	TUE 12/2, 7 PM	WED 12/3, 1 AM	WED 12/3, 7 AM	WED 12/3, 1 PM	WED 12/3, 7 PM	THU 12/4, 1 AM	THU 12/4, 7 AM	THU 12/4, 1 PM	THU 12/4, 7 PM	FRI 12/5, 1 AM	FRI 12/5, 7 AM
0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%
0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"

Precipitation Chance (%)



Rainfall (inches)



Erosion Control

Existing vegetation

PASS

Photos



38.27179, -121.29525



38.27179, -121.29525

Runoff Controls

Stabilized swales

PASS

Photos



38.27179, -121.29525

Velocity / energy dissipation

PASS

Photos



38.27179, -121.29525

Track-Out Control

Was track out observed leaving the project boundary?

Answer: YES

Photos



Install construction entrance
38.27179, -121.29525

Wind Erosion Control

Was dust observed leaving the project boundary?

Answer: NO

Dust suppression with water

PASS

Photos



38.27179, -121.29525

Non-Storm Water Control

Was water observed to be discharging from the project?

PASS

Answer: NO

Photos



38.27179, -121.29525

If yes, was it being pumped or siphoned off site?

Answer: NO

Good Housekeeping

Concrete washout devices

CORRECTIVE ACTION REQUIRED

Photos



Full, needs dumping
38.27179, -121.29525

Waste bins

PASS

Photos



38.27179, -121.29525