

Sample Thermal Imaging Report

Thermal Scan Device: FLIR Camera

Inspection Date: 10 March 2026

Thermal Observation 1: Elevated temperature detected near the living room wall crack (approx. 35°C).

Thermal Observation 2: Cooler region detected in bedroom ceiling damp area (approx. 18°C).

Thermal Images

