

Amit Jadhav

From: Venkatesh P I Service <venkatesh.p@in.sungrowpower.com>
Sent: 15-09-26 01:00 PM
To: Amit Jadhav; Kotha Ganesh I Service; Sathishkumar Manigandan
Cc: Pranesh Joshi I Sungrow India; Sreerangam Ravikiran I Sungrow India; Danish Asrar; Ashwini Pandey; Sanjay Pyati; Nazir Ahmad; Chandra Kumar Mishra; Mayur Kanchan; Anbukkaniraja K; Rahul Sambare; Anantharaja P | Service; Sreerangam Ravikiran I Sungrow India
Subject: RE: Amplus site_ ICR 3 Inverter no 3.1 bus duct breaker tripping issue.

Dear Sathish Ji/ Amit Ji,

With reference to the trailing mail, I would like to clarify that the inverter is a grid-following inverter, which means the inverter follows and synchronizes with the voltage and frequency available from the grid. The inverter does not independently control or increase the grid voltages and phase angles. Further, as per the available event sequence, the ACB tripped with an "Ig-fault" indication before the inverter trip occurred. Therefore, the ACB operation appears to have occurred prior to the inverter protection trip.

In view of the above, we request you to please verify the ACB protection system and the associated connected circuits at the grid side, including the Ig-fault protection, sensing circuit, CT connections, protection settings, and connected AC circuits, to identify the reason for the ACB operation.

Best Regards

Venkatesh Kumar

Zonal Manager – Service | South | PV & BESS

Mobile: +91-9160709525

Venkatesh.p@in.sungrowpower.com

SUNGROW INDIA PVT. LTD.

India HQ : 304,3rd Floor, Picasso Centre, Golf Course Extension Road, Sector -61,Gurugram,Haryana-122102



West : Awfis Vashi, 18th Floor, Cyberone, opp. CIDCO Exhibition Centre, Sector 30, Vashi, Navi Mumbai, Maharashtra 400703

South : 1104-1106, 11th Floor A-Wing, Mittal Tower, MG Road, Bangalore-560001

Factory Add: Survey No.250/3, T-Begur Village, Kasaba Hobli, Nelamangala Taluk, Bangalore, Karnataka-562123

New Factory: Survey No 79/4 & 206, Magadi Taluk, Soluru Hobli, Lakkenahalli, Ramanagara, Karnataka, 562127

Service Helpline : 8287233233, Service Email : service@in.sungrowpower.com

India Website: ind.sungrowpower.com

From: Amit Jadhav <amit.jadhav@essensrenewable.com>

Sent: 15 September 2026 11:07

To: Venkatesh P I Service <venkatesh.p@in.sungrowpower.com>; Kotha Ganesh I Service <ganesh.k@in.sungrowpower.com>; Sathishkumar Manigandan <sathishkumar.mani@essensrenewable.com>

Cc: Pranesh Joshi I Sungrow India <pranesh.j@in.sungrowpower.com>; Sreerangam Ravikiran I Sungrow India <sreerangam.ravi@in.sungrowpower.com>; Danish Asrar <danish.asrar@essensrenewable.com>; Ashwini Pandey <ashwini.pandey@essensrenewable.com>; Sanjay Pyati <sanjay.pyati@essensrenewable.com>; Nazir Ahmad <nazir.ahmad@essensrenewable.com>; chandrakumar.mishra <chandrakumar.mishra@essensrenewable.com>; Mayur