## First Notice of Loss

2023-09-08T04:00:00Z

Claim Number: ERA23LA271

Incident Date: 2023-06-18T08:00:00Z

Flight

Operator: nan

Purpose: INST

Airport of Record: Seymour Air Park

Incident Location:

35.812279, -83.774642, Seymore, Tennessee, United States

Aircraft

Make: CESSNA

Model: 172

Category: AIR

Amateur Built: False

Number of Engines: 1

Damage

Cause: The flight instructor's failure to properly configure the wing flaps for a soft-field takeoff on a short runway, which resulted in a runway overrun and collision with trees.

Damage: Substantial

Condition: VMC

Injuries

Highest Injury Level: Serious

Number of Serious Injuries: 1

Number of MInor Injuries: 3



## Airplance Insurance Policy

Policy Number 16
Active: From 01/01/2024 to 31/12/2024
Policy Holder: nan
For Purpose: INST
Airport of Record: Seymour Air Park
Aircraft
Make & Model: CESSNA 172
Category: AIR
Coverage:
Covered aircrafts:
Airplanes
Gliders
Helicopters
Gyrocopters
Excluded:
Anything else
Covered:
Pilot Mistakes or failures
Mechanical due to engine issues, oil starvation, fuel exhaust
Student or instructor mistakes or failures
Unregistered plane or uncertified pilot
Excluded:
Collision with animals, trees or environment