First Notice of Loss

2023-03-23T04:00:00Z

Claim Number: CEN23LA086

Incident Date: 2023-01-10T13:40:00Z

Flight

Operator: SMITH HELICOPTERS INC

Purpose: AOBV

Airport of Record: nan

Incident Location:

28.255431, -98.739375, Fowlerton, Texas, United States

Aircraft

Make: ROBINSON HELICOPTER

Model: R44

Category: HELI

Amateur Built: False

Number of Engines: 1

Damage

Cause: The pilot's failure to maintain clearance with trees, which resulted in an uncontrollable spin due to tail rotor damage.

Damage: Substantial

Condition: VMC

Injuries

Highest Injury Level: Minor

Number of Serious Injuries: 0

Number of MInor Injuries: 1



Airplance Insurance Policy

Policy Number 50
Active: From 01/01/2024 to 31/12/2024
Policy Holder: SMITH HELICOPTERS INC
For Purpose: AOBV
Airport of Record: nan
Aircraft
Make & Model: ROBINSON HELICOPTER R44
Category: HELI
Coverage:
Covered aircrafts:
Airplanes
Gliders
Helicopters
Gyrocopters
Excluded:
Anything else
Covered:
Pilot Mistakes or failures
Collision with animals, trees or environment
Mechanical due to engine issues, oil starvation, fuel exhaust
Student or instructor mistakes or failures
Unregistered plane or uncertified pilot
Excluded:
Anything else