First Notice of Loss

2023-08-31T04:00:00Z

Claim Number: ERA23LA287

Incident Date: 2023-07-04T19:30:00Z

Flight

Operator: nan

Purpose: AOBV

Airport of Record: MYRTLE BEACH INTL

Incident Location:

33.679741, -78.928321, Myrtle Beach, South Carolina, United States

Aircraft

Make: ROBINSON HELICOPTER

Model: R44

Category: HELI

Amateur Built: False

Number of Engines: 1

Damage

Cause: The pilot's failure to maintain control of the helicopter during a hover taxi, which resulted in a rollover.

Damage: Substantial

Condition: VMC

Injuries

Highest Injury Level: Serious

Number of Serious Injuries: 1

Number of MInor Injuries: 3

