First Notice of Loss

2023-08-31T04:00:00Z

Claim Number: ERA23LA287

Incident Date: 2023-07-04T19:30:00Z

Flight

Operator: nan

Purpose: AOBV

Airport of Record: MYRTLE BEACH INTL

Incident Location:

33.679741, -78.928321, Myrtle Beach, South Carolina, United States

Aircraft

Make: ROBINSON HELICOPTER

Model: R44

Category: HELI

Amateur Built: False

Number of Engines: 1

Damage

Cause: The pilot's failure to maintain control of the helicopter during a hover taxi, which resulted in a rollover.

Damage: Substantial

Condition: VMC

Injuries

Highest Injury Level: Serious

Number of Serious Injuries: 1

Number of MInor Injuries: 3



Airplance Insurance Policy

Policy Number 11
Active: From 01/01/2024 to 31/12/2024
Policy Holder: nan
For Purpose: AOBV
Airport of Record: MYRTLE BEACH INTL
Aircraft
Make & Model: ROBINSON HELICOPTER R44
Category: HELI
Coverage:
Covered aircrafts:
Airplanes
Gliders
Gyrocopters
Excluded:
Helicopters
Covered:
Pilot Mistakes or failures
Collision with animals, trees or environment
Mechanical due to engine issues, oil starvation, fuel exhaust
Student or instructor mistakes or failures
Unregistered plane or uncertified pilot
Excluded:
Anything else