## First Notice of Loss

2023-04-20T04:00:00Z Claim Number: WPR23LA126 Incident Date: 2023-03-11T12:30:00Z Flight Operator: nan Purpose: PERS Airport of Record: nan **Incident Location:** 40.17, -111.13, Strawberry Reservoir, Utah, United States Aircraft Make: TRENDAK Model: TAURUS Category: GYRO Amateur Built: True Number of Engines: 1 Damage Cause: The pilot's failure to maintain clearance from the snow-covered lake while flying at a low altitude. Damage: Substantial

Injuries

Condition: VMC

Highest Injury Level: Minor

Number of Serious Injuries: 0

Number of MInor Injuries: 2



## Airplance Insurance Policy

Policy Number 41
Active: From 01/01/2024 to 31/12/2024
Policy Holder: nan
For Purpose: PERS
Airport of Record: nan
Aircraft
Make & Model: TRENDAK TAURUS
Category: GYRO
Coverage:
Covered aircrafts:
Airplanes
Gliders
Excluded:
Helicopters
Gyrocopters
Covered:
Pilot Mistakes or failures
Collision with animals, trees or environment
Mechanical due to engine issues, oil starvation, fuel exhaust
Student or instructor mistakes or failures
Unregistered plane or uncertified pilot
Excluded:
Anything else