

Qualification Pack



CNC Programmer

QP Code: CSC/Q0401

Version: 1.0

NSQF Level: 4

Capital Goods & Strategic Skill Council || 1st Floor, L-29, Outer Circle, Connaught Place
New Delhi - 110001 || email: coo@cgsc.in

Qualification Pack

Contents

CSC/Q0401: CNC Programmer	3
<i>Brief Job Description</i>	3
Applicable National Occupational Standards (NOS)	3
<i>Compulsory NOS</i>	3
<i>Qualification Pack (QP) Parameters</i>	3
CSC/N0401: Program computer numerically controlled (CNC) machines	5
CSC/N1335: Use basic health and safety practices at the workplace	19
CSC/N1336: Work effectively with others	28
Assessment Guidelines and Weightage	31
<i>Assessment Guidelines</i>	31
<i>Assessment Weightage</i>	32
Acronyms	33
Glossary	34

Qualification Pack

CSC/Q0401: CNC Programmer

Brief Job Description

Produce the component program using manual data input or by use of a remote computer, saving the prepared program on the machine controller from the computer. This involves understanding the CNC machine tools used in the process, their application and programming, editing and proving process, in adequate depth to provide a sound basis for carrying out the activities.

Personal Attributes

Basic communication, numerical and computational abilities. Openness to learning, ability to plan and organize own work and identify and solve problems in the course of working. Understanding the need to take initiative and manage self and work to improve efficiency and effectiveness.

Applicable National Occupational Standards (NOS)

Compulsory NOS:

1. [CSC/N0401: Program computer numerically controlled \(CNC\) machines](#)
2. [CSC/N1335: Use basic health and safety practices at the workplace](#)
3. [CSC/N1336: Work effectively with others](#)

Qualification Pack (QP) Parameters

Sector	Capital Goods
Sub-Sector	Machine Tools
Occupation	Design
Country	India
NSQF Level	4
Credits	NA
Aligned to NCO/ISCO/ISIC Code	NCO-2004/NIL
Minimum Educational Qualification & Experience	Diploma (Mechanical Engineering) with 1-2 Years of experience Working with CNC machine.

Qualification Pack

Minimum Level of Education for Training in School	
Pre-Requisite License or Training	NA
Minimum Job Entry Age	18 Years
Last Reviewed On	24/11/2017
Next Review Date	10/08/2025
Deactivation Date	17/01/2025
NSQC Approval Date	19/05/2015
Version	1.0
Reference code on NQR	2015/CCM/GCSC/00120
NQR Version	1.0

Qualification Pack

CSC/N0401: Program computer numerically controlled (CNC) machines

Description

This unit covers making programs for and proving out of parts on Computer Numerically Controlled (CNC) lathes and machining centers. Programming can be done manually or using CAM software. The program is transferred to the machine's controller by entering it at the console, transmitting it through a wired link, or copying it through a data storage device like a flash card.

Scope

This unit/ task covers the following:

- Work safely
- Prepare for programming CNC machine for production
- Carry out programming for CNC machine
- Test and prove the program on the CNC Machine

Elements and Performance Criteria

Work safely

To be competent, the user/individual on the job must be able to:

- PC1.** comply with health and safety, environmental and other relevant regulations and guidelines at work
- PC2.** adhere to procedures and guidelines for personal protective equipment (PPE) and other relevant safety regulations while programming CNC machines
- PC3.** work following laid down procedures and instructions
- PC4.** ensure that machine guards are in place and are correctly adjusted
- PC5.** read and understand safety instructions, warning signs on the machine
- PC6.** ensure work area is clean and safe from hazards
- PC7.** ensure that all tools, equipment, power tool cables, extension leads are in a safe and usable condition

Prepare for programming CNC machine for production

To be competent, the user/individual on the job must be able to:

- PC8.** obtain job specification from a valid and approved source (Valid sources: job instruction sheet/job card; work drawings and instructions; planning documentation; quality control documents; operation sheets; process specifications; instructions from supervisor)

Qualification Pack

- PC9.** read and establish job requirements from the job specification document accurately (Job specification documents: detailed component drawings; approved sketches/illustrations; national, international and organisational standards; reference tables and charts; fabrication/casting drawings; operational diagrams; contractual specifications Job requirements: raw materials or components required (type, quality, quantity); dimensions; limits and tolerances; surface finish requirements; operations required (list, sequence and procedures where applicable); shape or profiles to be generated; instruments and tools to be used; form tolerances (flatness, concentricity, etc.); cycle time, production rate; projections orthographic (first angle, third angle), isometric (including exploded, oblique); reference points, lines, edges and surfaces; dimensions (baseline, continuous); workholding devices)
- PC10.** follow job instructions, assembly drawings and laid down procedures at all times
- PC11.** report and rectify incorrect and inconsistent information in job specification documents as per organization procedures
- PC12.** use and extract information from reference charts, tables, graphs and standards Information pertaining to: tapping sizes and threads; cutting parameters feeds, speed, depth of cut; machining symbols and tolerances
- PC13.** prepare the work area as per procedure or operational specification
- PC14.** conduct a preliminary check of the readiness of the program so that the CNC machine operates correctly (CNC machines: 2-axis CNC lathes, 3-axis machining centers (VMC, HMC), > 3 axes machining centers (3/4 axes) Checks: ensure that all tool length/wear/radius offsets are correctly entered; for finishing operations, adjust offsets to get slightly oversize/undersize dimensions to ensure that the part does not get rejected; run the program in dry run mode to ensure that there are no collisions between the tool and workpiece/work holding devices; check tool change positions are safe and clear of the workpiece and work holding devices; ensure that correct tools are selected at the appropriate points in the program; check if the tool paths are executed safely and correctly; ensure that the auxiliary functions operate at the correct point in the program (spindle start/stop, coolant flow, program optional stop); run the program, in single block mode wherever necessary; measure the dimensions of the component on the machine and make necessary corrections in tool offsets; inspect the component for all dimensions and record findings in specified formats; make necessary changes in tool length / wear / radius offsets to correct dimension errors; run the next component; ensure that all dimensions are within specifications; if dimensions are not within specifications, correct using appropriate actions; repeat this till parts come within specifications without any correction requirement)
- PC15.** determine what operational objectives and targets need to be achieved and how best the machine needs to be programmed to achieve this CNC programming (Operations: preparing, loading, storing in appropriate format, proving the part program, trial runs)
- PC16.** extract and use information from engineering drawings and related specifications in relation to work undertaken
- PC17.** identify tool requirements from tooling layout and assess their suitability
- PC18.** identify suitable workholding or fixturing device as per the job requirement
- PC19.** ensure the correct and latest part-program is uploaded onto the CNC system

Carry out programming for CNC machine

To be competent, the user/individual on the job must be able to:

- PC20.** make the CNC program with commands for tool motions, spindle motions, miscellaneous functions and tool change, in syntax corresponding to the machine and control system on which the component will be machined

Qualification Pack

- PC21.** make CNC program using various ways such as writing it on paper or in a computer's text editor, or using CAM software or controllers on machine (Ways: written, directly entered into the machine controller, using computer software-CAM software)
- PC22.** ensure that the part program is efficient and results in minimal cycle time, with optimal cutting parameters and no unnecessary tool motions
- PC23.** use subprograms and canned cycles, to reduce program size and input time and avoid memory overflow on the machine
- PC24.** transfer the program to the machine by entering it at the console or transmitting it through a wired link or through a data transfer device
- PC25.** follow the correct procedures for calling up the program and dealing with any error messages or faults
- PC26.** handle the typical problems that can occur with the programming, loading and editing activities effectively using approved procedures
- PC27.** save the proven program in the appropriate storage medium, such as paper, computer hard disk, etc. and location
- PC28.** complete relevant documentation as per organizational procedure
- PC29.** leave the work area in a safe and tidy condition on completion of the activities

Test and prove the program on the CNC Machine

To be competent, the user/individual on the job must be able to:

- PC30.** obtain appropriate equipment or tools needed as per job requirements
- PC31.** ensure that all measuring equipment is calibrated and approved for usage
- PC32.** ensure that the tools and fixtures are in usable condition (eg. free from breakage, damage, calibration, etc.)
- PC33.** pre-set the tooling appropriately using setting jigs/fixtures
- PC34.** seek any necessary instruction/training on the operation of the machine where required
- PC35.** mount tools in the correct positions in the tool turret or magazine
- PC36.** check that the tools have been mounted in positions corresponding to tool numbers in the part program
- PC37.** measure tool and work offset data - X and Z offsets for lathes; work offsets, length offsets and tool radius for machining centers
- PC38.** ensure that the component is free of burrs, chips or other material adhering to its butting surfaces
- PC39.** mount the part on machine firmly in the specified work holding devices, with the appropriate clamping forces
- PC40.** enter work offset and tool data on the machine X and Z offsets, tool orientation and nose radius for lathes; length offsets and tool radius for machining centers
- PC41.** ensure that tool data has been entered in offset number corresponding to the tool offset numbers in the part program (Tool data: tool length and radius/diameter offsets for milling tools; X, Z tool offsets for turning tools; tool nose radius for turning tools)
- PC42.** deal with error messages and faults on the program or equipment
- PC43.** cut a trial part using single block run, dry run and feed and speed override controls
- PC44.** edit the program and adjust tool and wear offsets to correct any dimensional errors on the part

Qualification Pack

- PC45.** ensure that the trial part conforms to drawing specifications in terms of dimensions, surface finishes and geometrical parameters like concentricity, parallelism, runout, etc.
- PC46.** hand-over the machine to the machine operator for machining the batch of parts, along with relevant instructions and documentation on periodic inspection of components, change of worn out tools
- PC47.** correct the tool wear offsets whenever required, based on the results of the period inspection
- PC48.** change worn out tools and indexable inserts whenever required
- PC49.** cut a trial part and correct any dimensional inaccuracies by adjusting the tool offsets or wear offsets after every change of a worn out tool
- PC50.** return worn out cutting tools, workholding device/fixtures/instruments/drawings to store
- PC51.** ensure that there is no damage to the tool/fixture while doing the prove-out
- PC52.** shut down the equipment to a safe condition on conclusion of the activities
- PC53.** deal promptly and effectively with problems within span of responsibility and control and report those that cannot be solved

Knowledge and Understanding (KU)

The individual on the job needs to know and understand:

- KU1.** legislation, standards, policies, and procedures followed in the company relevant to own employment and performance conditions
- KU2.** relevant health and safety requirements applicable in the work place
- KU3.** importance of working in clean and safe environment
- KU4.** own job role and responsibilities and sources for information pertaining to employment terms, entitlements, job role and responsibilities
- KU5.** reporting structure, inter-dependent functions, lines and procedures in the work area
- KU6.** relevant people and their responsibilities within the work area
- KU7.** escalation matrix and procedures for reporting work and employment related issues
- KU8.** documentation and related procedures applicable in the context of employment and work
- KU9.** importance and purpose of documentation in context of employment and work
- KU10.** specific safe working practices, CNC programming procedures and environmental regulations that must be observed (Safe working practices and procedures: use the appropriate reference manuals and programming codes to suit the machine controller; use the correct and updated version of the program; ensure that tool and work offsets are entered correctly; ensure that the program does not result in tool collision with the workpiece or work holding devices; ensure that the workpiece and tools are clamped firmly; use the correct control program and ensure it is correctly loaded into the machine controller; wear personal protective equipment (PPE); use correctly fitting overalls, boots and safety glasses; ensure that long hair tied back or netted; remove any jewellery or other items that can become entangled in the machinery)
- KU11.** hazards associated with carrying out the machining operations on a CNC machine and how can they be minimized (Hazards: automatic, high speed machine movements; revolving/moving parts of machinery; airborne and hot metal particles and fluids; sharp cutting tools; parts dropping from material handling devices; burrs and sharp edges on component; use of power operated chucks; moving machinery in aisles)

Qualification Pack

- KU12.** personal protective equipment to be used during the machining activities on a CNC machine and where can it be obtained
- KU13.** safety mechanism on the machine and how to check if they are functioning properly (Safety mechanism on the machine: emergency stop button; feed hold button)
- KU14.** types and sources of appropriate job specifications
- KU15.** common terminology used in CNC programming features of produced CNC program (Features: program number; program documentation in comments - part number, part name, programmer, date of program, tool names, operation names; motion commands; tool change positioning and command; tool numbers and offset numbers; subprograms and canned cycles; tool nose radius compensation commands; spindle, feed rate and coolant commands)
- KU16.** selection of strategies based on material and fixturing, holding and clamping force
- KU17.** the factors which will determine selection and use of tungsten carbide and tips (Factors: hardness of the component material; machinability characteristics of the material; tolerances to be achieved; surface finish to be achieved; geometrical accuracies like ovality, straightness and flatness to be achieved; rigidity of work holding)
- KU18.** importance of tool selection based on material, finish required and tolerances achieved
- KU19.** importance of cutter engagement and exit
- KU20.** factors affecting tool life
- KU21.** importance and effect of the depth of cut, RPM and feed
- KU22.** how to read and interpret first and third angle component drawings
- KU23.** how to extract information from engineering drawings or data and related specifications
- KU24.** how to use the function keys and user interface of the machine control system
- KU25.** determination and entry of work and tool offsets, tool wear data
- KU26.** main features and working parts of the CNC machine, and the accessories that can be used (CNC machines: 2-axis CNC lathes, 3-axis machining centers (VMC, HMC), > 3 axes machining centers (3/4 axes)
- KU27.** importance of following specified machining sequences and procedures
- KU28.** importance of ensuring suitability of workpieces/materials and consumables for the specified job and related procedures
- KU29.** importance and procedures to ensure that tools and equipment are in a safe and usable condition
- KU30.** various CNC operations that can be performed, and the methods and equipment used
- KU31.** methods of setting the work-holding devices, and the tools and equipment that can be used
- KU32.** various tool holding devices that are used, and the methods of correctly mounting and securing the cutting tools to the tool holders
- KU33.** how to set the machine controller in the program and editing mode, and enter or download the prepared program (Mode of machine control: program operating and control buttons)
- KU34.** automatic tool changers, pallet changers, rotary tables and part auto loaders used
- KU35.** how to position and identify the tools in relationship to the operating program
- KU36.** function of error messages, and appropriate subsequent action

Qualification Pack

- KU37.** importance of proving the program, how to do it and selecting the correct proving tools (Tools: single block mode, jog, dry run, graphical tool path simulation, search facilities, program save/store facilities, edit facilities, spindle speed and feed rate override controls, program input facilities insert, delete, modify, tool data input facilities tool offset, nose radius)
- KU38.** need for storing program storage devices safely and correctly, away from contaminants and electromagnetic sources
- KU39.** quality control procedures that are used, inspection checks to be carried out, and the equipment that will need to be used
- KU40.** importance to report problems in a timely manner
- KU41.** importance of writing programs that are easily editable or correctable by the next person
- KU42.** methods of checking quality of the shaped components against the required quality standards
- KU43.** production cost, machine hour rate, raw material cost, tool cost, coolant cost, overheads, cycle time, idle time, cost of machine idling, part rejection cost
- KU44.** selection of cutting tools, tool materials, chip breaker geometry, selecting cutting parameters from tool catalogues, selecting coolant
- KU45.** relationship between surface finish, tool nose radius and feed rate
- KU46.** impact of depth of cut on chatter, surface finish
- KU47.** range of materials used in common engineering applications
- KU48.** how to identify materials by their physical properties

Generic Skills (GS)

User/individual on the job needs to know how to:

- GS1.** read and interpret information correctly from various job specification documents, health and safety instructions, memos, etc. applicable to the job in English and/or local language
- GS2.** fill up appropriate technical forms, process charts, activity logs as per organizational format in English and/or local language
- GS3.** undertake numerical computations and calculation (Numerical computations: addition, subtraction, multiplication, division, fractions and decimals, percentages and proportions, simple ratios and averages, basic algebra and trigonometry)
- GS4.** identify and draw various basic, compound and solid shapes as per dimensions given (Basic shapes: square, rectangle, triangle, circle, quadrilaterals Compound shapes: involving squares, rectangles, triangles, circles, semi-circles, quadrants of a circle Solid shapes: cube, rectangular prism, cylinder)
- GS5.** use appropriate measuring techniques and units of measurement
- GS6.** use appropriate units and number systems to express degree of accuracy (Units and number systems representing degree of accuracy: decimals places, significant figures, fractions as a decimal quantity)
- GS7.** interpret and express tolerance in terms of limits on dimensions
- GS8.** calculation of the value of angles in a triangle (Angles in a triangle: right-angled, isosceles, equilateral, scalene)
- GS9.** convey and share technical information clearly using appropriate language

Qualification Pack

- GS10.** check and clarify task-related information
- GS11.** liaise with appropriate authorities using correct protocol
- GS12.** communicate with people in respectful form and manner in line with organizational protocol
- GS13.** plan, prioritize and sequence work operations as per job requirements
- GS14.** organize and analyze information relevant to work
- GS15.** basic concepts of shop-floor work productivity including waste reduction, efficient material usage and optimization of time
- GS16.** exercise restraint while expressing dissent and during conflict situations
- GS17.** avoid and manage distractions to be disciplined at work
- GS18.** manage own time for achieving better results
- GS19.** work in a team in order to achieve better results
- GS20.** identify and clarify work roles within a team
- GS21.** communicate and cooperate with others in the team for better results
- GS22.** seek assistance from fellow team members
- GS23.** identify problems with work planning, procedures, output and behavior and their implications
- GS24.** prioritize and plan for problem solving
- GS25.** communicate problems appropriately to others
- GS26.** identify sources of information and support for problem solving
- GS27.** seek assistance and support from other sources to solve problems
- GS28.** identify effective resolution techniques
- GS29.** select and apply resolution techniques
- GS30.** seek evidence for problem resolution
- GS31.** undertake and express new ideas and initiatives to others
- GS32.** modify work plan to overcome unforeseen difficulties or developments that occur as work progresses
- GS33.** participate in improvement procedures including process, quality and internal/external customer/supplier relationships
- GS34.** enhance ones competencies in new and different situations and contexts to achieve more
- GS35.** participate in on-the-job and other learning, training and development interventions and assessments
- GS36.** clarify task related information with appropriate personnel or technical adviser
- GS37.** seek to improve and modify own work practices
- GS38.** maintain current knowledge of application standards, legislation, codes of practice and product/process developments

Qualification Pack

Assessment Criteria

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
<i>Work safely</i>	2	9	-	-
PC1. comply with health and safety, environmental and other relevant regulations and guidelines at work	1	2	-	-
PC2. adhere to procedures and guidelines for personal protective equipment (PPE) and other relevant safety regulations while programming CNC machines	1	2	-	-
PC3. work following laid down procedures and instructions	-	1	-	-
PC4. ensure that machine guards are in place and are correctly adjusted	-	1	-	-
PC5. read and understand safety instructions, warning signs on the machine	-	1	-	-
PC6. ensure work area is clean and safe from hazards	-	1	-	-
PC7. ensure that all tools, equipment, power tool cables, extension leads are in a safe and usable condition	-	1	-	-
<i>Prepare for programming CNC machine for production</i>	7	17	-	-
PC8. obtain job specification from a valid and approved source (Valid sources: job instruction sheet/job card; work drawings and instructions; planning documentation; quality control documents; operation sheets; process specifications; instructions from supervisor)	-	1	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC9. read and establish job requirements from the job specification document accurately (Job specification documents: detailed component drawings; approved sketches/illustrations; national, international and organisational standards; reference tables and charts; fabrication/casting drawings; operational diagrams; contractual specifications Job requirements: raw materials or components required (type, quality, quantity); dimensions; limits and tolerances; surface finish requirements; operations required (list, sequence and procedures where applicable); shape or profiles to be generated; instruments and tools to be used; form tolerances (flatness, concentricity, etc.); cycle time, production rate; projections orthographic (first angle, third angle), isometric (including exploded, oblique); reference points, lines, edges and surfaces; dimensions (baseline, continuous); workholding devices)	1	1	-	-
PC10. follow job instructions, assembly drawings and laid down procedures at all times	1	1	-	-
PC11. report and rectify incorrect and inconsistent information in job specification documents as per organization procedures	1	1	-	-
PC12. use and extract information from reference charts, tables, graphs and standards Information pertaining to: tapping sizes and threads; cutting parameters feeds, speed, depth of cut; machining symbols and tolerances	1	1	-	-
PC13. prepare the work area as per procedure or operational specification	-	1	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC14. conduct a preliminary check of the readiness of the program so that the CNC machine operates correctly (CNC machines: 2-axis CNC lathes, 3-axis machining centers (VMC, HMC), > 3 axes machining centers (3/4 axes) Checks: ensure that all tool length/wear/radius offsets are correctly entered; for finishing operations, adjust offsets to get slightly oversize/undersize dimensions to ensure that the part does not get rejected; run the program in dry run mode to ensure that there are no collisions between the tool and workpiece/work holding devices; check tool change positions are safe and clear of the workpiece and work holding devices; ensure that correct tools are selected at the appropriate points in the program; check if the tool paths are executed safely and correctly; ensure that the auxiliary functions operate at the correct point in the program (spindle start/stop, coolant flow, program optional stop); run the program, in single block mode wherever necessary; measure the dimensions of the component on the machine and make necessary corrections in tool offsets; inspect the component for all dimensions and record findings in specified formats; make necessary changes in tool length / wear / radius offsets to correct dimension errors; run the next component; ensure that all dimensions are within specifications; if dimensions are not within specifications, correct using appropriate actions; repeat this till parts come within specifications without any correction requirement)	-	2	-	-
PC15. determine what operational objectives and targets need to be achieved and how best the machine needs to be programmed to achieve this CNC programming (Operations: preparing, loading, storing in appropriate format, proving the part program, trial runs)	1	1	-	-
PC16. extract and use information from engineering drawings and related specifications in relation to work undertaken	1	2	-	-
PC17. identify tool requirements from tooling layout and assess their suitability	1	2	-	-
PC18. identify suitable workholding or fixturing device as per the job requirement	-	2	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC19. ensure the correct and latest part-program is uploaded onto the CNC system	-	2	-	-
<i>Carry out programming for CNC machine</i>	2	15	-	-
PC20. make the CNC program with commands for tool motions, spindle motions, miscellaneous functions and tool change, in syntax corresponding to the machine and control system on which the component will be machined	1	2	-	-
PC21. make CNC program using various ways such as writing it on paper or in a computer's text editor, or using CAM software or controllers on machine (Ways: written, directly entered into the machine controller, using computer software-CAM software)	1	2	-	-
PC22. ensure that the part program is efficient and results in minimal cycle time, with optimal cutting parameters and no unnecessary tool motions	-	2	-	-
PC23. use subprograms and canned cycles, to reduce program size and input time and avoid memory overflow on the machine	-	2	-	-
PC24. transfer the program to the machine by entering it at the console or transmitting it through a wired link or through a data transfer device	-	2	-	-
PC25. follow the correct procedures for calling up the program and dealing with any error messages or faults	-	1	-	-
PC26. handle the typical problems that can occur with the programming, loading and editing activities effectively using approved procedures	-	1	-	-
PC27. save the proven program in the appropriate storage medium, such as paper, computer hard disk, etc. and location	-	1	-	-
PC28. complete relevant documentation as per organizational procedure	-	1	-	-
PC29. leave the work area in a safe and tidy condition on completion of the activities	-	1	-	-
<i>Test and prove the program on the CNC Machine</i>	14	34	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC30. obtain appropriate equipment or tools needed as per job requirements	1	2	-	-
PC31. ensure that all measuring equipment is calibrated and approved for usage	-	1	-	-
PC32. ensure that the tools and fixtures are in usable condition (eg. free from breakage, damage, calibration, etc.)	-	1	-	-
PC33. pre-set the tooling appropriately using setting jigs/fixtures	1	2	-	-
PC34. seek any necessary instruction/training on the operation of the machine where required	-	1	-	-
PC35. mount tools in the correct positions in the tool turret or magazine	1	2	-	-
PC36. check that the tools have been mounted in positions corresponding to tool numbers in the part program	1	1	-	-
PC37. measure tool and work offset data - X and Z offsets for lathes; work offsets, length offsets and tool radius for machining centers	1	2	-	-
PC38. ensure that the component is free of burrs, chips or other material adhering to its butting surfaces	-	1	-	-
PC39. mount the part on machine firmly in the specified work holding devices, with the appropriate clamping forces	-	2	-	-
PC40. enter work offset and tool data on the machine X and Z offsets, tool orientation and nose radius for lathes; length offsets and tool radius for machining centers	1	2	-	-
PC41. ensure that tool data has been entered in offset number corresponding to the tool offset numbers in the part program (Tool data: tool length and radius/diameter offsets for milling tools; X, Z tool offsets for turning tools; tool nose radius for turning tools)	1	1	-	-
PC42. deal with error messages and faults on the program or equipment	1	1	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC43. cut a trial part using single block run, dry run and feed and speed override controls	1	1	-	-
PC44. edit the program and adjust tool and wear offsets to correct any dimensional errors on the part	1	1	-	-
PC45. ensure that the trial part conforms to drawing specifications in terms of dimensions, surface finishes and geometrical parameters like concentricity, parallelism, runout, etc.	1	1	-	-
PC46. hand-over the machine to the machine operator for machining the batch of parts, along with relevant instructions and documentation on periodic inspection of components, change of worn out tools	1	1	-	-
PC47. correct the tool wear offsets whenever required, based on the results of the period inspection	1	1	-	-
PC48. change worn out tools and indexable inserts whenever required	1	1	-	-
PC49. cut a trial part and correct any dimensional inaccuracies by adjusting the tool offsets or wear offsets after every change of a worn out tool	-	1	-	-
PC50. return worn out cutting tools, workholding device/fixtures/instruments/drawings to store	-	2	-	-
PC51. ensure that there is no damage to the tool/fixture while doing the prove-out	-	2	-	-
PC52. shut down the equipment to a safe condition on conclusion of the activities	-	2	-	-
PC53. deal promptly and effectively with problems within span of responsibility and control and report those that cannot be solved	-	2	-	-
NOS Total	25	75	-	-

Qualification Pack

National Occupational Standards (NOS) Parameters

NOS Code	CSC/N0401
NOS Name	Program computer numerically controlled (CNC) machines
Sector	Capital Goods
Sub-Sector	Machine Tools, Dies, Moulds and Press Tools, Plastics Manufacturing Machinery, Textile Manufacturing Machinery, Process Plant Machinery, Electrical and Power Machinery, Light Engineering Goods
Occupation	Design
NSQF Level	4
Credits	TBD
Version	1.0
Last Reviewed Date	24/11/2017
Next Review Date	31/03/2022
NSQC Clearance Date	19/05/2015

Qualification Pack

CSC/N1335: Use basic health and safety practices at the workplace

Description

This OS unit is about knowledge and practices relating to health, safety and security that candidates need to use in the workplace. It covers responsibilities towards self, others, assets and the environment.

Elements and Performance Criteria

Health and safety

To be competent, the user/individual on the job must be able to:

- PC1.** use protective clothing/equipment for specific tasks and work conditions (Protective clothing: leather or asbestos gloves, flame proof aprons, flame proof overalls buttoned to neck, cuffless (without folds), trousers, reinforced footwear, helmets/hard hats, cap and shoulder covers, ear defenders/plugs, safety boots, knee pads, particle masks, glasses/goggles/visors Equipment: hand shields, machine guards, residual current devices, shields, dust sheets, respirator)
- PC2.** state the name and location of people responsible for health and safety in the workplace
- PC3.** state the names and location of documents that refer to health and safety in the workplace
- PC4.** identify job-site hazardous work and state possible causes of risk or accident in the workplace (Hazards: sharp edged and heavy tools; heated metals; oxyfuel and gas cylinders; welding radiation; hazardous surfaces(sharp, slippery, uneven, chipped, broken, etc.); hazardous substances(chemicals, gas, oxy-fuel, fumes, dust, etc.); physical hazards(working at heights, large and heavy objects and machines, sharp and piercing objects, tolls and machines, intense light, load noise, obstructions in corridors, by doors, blind turns, noise, over stacked shelves and packages, etc.) electrical hazards (power supply and points, loose and naked cables and wires, electrical machines and appliances, etc.) Possible causes of risk and accident: physical actions; reading; listening to and giving instructions; inattention; sickness and incapacity (such as drunkenness); health hazards (such as untreated injuries and contagious illness))
- PC5.** carry out safe working practices while dealing with hazards to ensure the safety of self and others (Safe working practices: using protective clothing and equipment; putting up and reading safety signs; handle tools in the correct manner and store and maintain them properly; keep work area clear of clutter, spillage and unsafe object lying casually; while working with electricity take all electrical precautions like insulated clothing, adequate equipment insulation, use of control equipment, dry work area, switch off the power supply when not required, etc.; safe lifting and carrying practices; use equipment that is working properly and is well maintained; take due measures for safety while working in confined places, trenches or at heights, etc. including safety harness, fall arrestors, etc.)
- PC6.** state methods of accident prevention in the work environment of the job role (Methods of accident prevention: training in health and safety procedures; using health and safety procedures; use of equipment and working practices (such as safe carrying procedures); safety notices, advice; instruction from colleagues and supervisors)
- PC7.** state location of general health and safety equipment in the workplace (General health and safety equipment: fire extinguishers; first aid equipment; safety instruments and clothing; safety installations(eg fire exits, exhaust fans))

Qualification Pack

- PC8.** inspect for faults, set up and safely use steps and ladders in general use (Ladder faults: corrosion of metal components, deterioration, splits and cracks timber components, imbalance, loose rungs, missing/ unfixed nuts or bolts, etc.) (Ladders set up: firm/level base, clip/lash down, leaning at the correct angle, etc.)
- PC9.** work safely in and around trenches, elevated places and confined areas
- PC10.** lift heavy objects safely using correct procedures
- PC11.** apply good housekeeping practices at all times (Good housekeeping practices: clean/tidy work areas, removal/disposal of waste products, protect surfaces)
- PC12.** identify common hazard signs displayed in various areas (Various areas: on chemical containers; equipment; packages; inside buildings; in open areas and public spaces, etc.)
- PC13.** retrieve and/or point out documents that refer to health and safety in the workplace (Documents: fire notices, accident reports, safety instructions for equipment and procedures, company notices and documents, legal documents (eg government notices))

Fire safety

To be competent, the user/individual on the job must be able to:

- PC14.** use the various appropriate fire extinguishers on different types of fires correctly (Types of fires: Class A: eg. ordinary solid combustibles, such as wood, paper, cloth, plastic, charcoal, etc.; Class B: flammable liquids and gases, such as gasoline, propane, diesel fuel, tar, cooking oil, and similar substances; Class C: eg. electrical equipment such as appliances, wiring, breaker panels, etc. (These categories of fires become Class A, B, and D fires when the electrical equipment that initiated the fire is no longer receiving electricity); Class D: combustible metals such as magnesium, titanium, and sodium (These fires burn at extremely high temperatures and require special suppression agents))
- PC15.** demonstrate rescue techniques applied during fire hazard
- PC16.** demonstrate good housekeeping in order to prevent fire hazards
- PC17.** demonstrate the correct use of a fire extinguisher

Emergencies, rescue and first-aid procedures

To be competent, the user/individual on the job must be able to:

- PC18.** demonstrate how to free a person from electrocution
- PC19.** administer appropriate first aid to victims where required eg. in case of bleeding, burns, choking, electric shock, poisoning etc.
- PC20.** demonstrate basic techniques of bandaging
- PC21.** respond promptly and appropriately to an accident situation or medical emergency in real or simulated environments
- PC22.** perform and organize loss minimization or rescue activity during an accident in real or simulated environments
- PC23.** administer first aid to victims in case of a heart attack or cardiac arrest due to electric shock, before the arrival of emergency services in real or simulated cases
- PC24.** demonstrate the artificial respiration and the CPR Process
- PC25.** participate in emergency procedures (Emergency procedures: raising alarm, safe/efficient, evacuation, correct means of escape, correct assembly point, roll call, correct return to work)
- PC26.** complete a written accident/incident report or dictate a report to another person, and send report to person responsible (Incident Report includes details of: name, date/time of incident, date/time of report, location, environment conditions, persons involved, sequence of events, injuries sustained, damage sustained, actions taken, witnesses, supervisor/manager notified)

Qualification Pack

Emergencies, rescue and first-aid procedures

To be competent, the user/individual on the job must be able to:

PC27. demonstrate correct method to move injured people and others during an emergency

Knowledge and Understanding (KU)

The individual on the job needs to know and understand:

- KU1.** names (and job titles if applicable), and where to find, all the people responsible for health and safety in a workplace
- KU2.** names and location of documents that refer to health and safety in the workplace
- KU3.** meaning of hazards and risks
- KU4.** health and safety hazards commonly present in the work environment and related precautions
- KU5.** possible causes of risk, hazard or accident in the workplace and why risk and/or accidents are possible
- KU6.** possible causes of risk and accident(Possible causes of risk and accident: physical actions; reading; listening to and giving instructions; inattention; sickness and incapacity (such as drunkenness); health hazards (such as untreated injuries and contagious illness))
- KU7.** methods of accident prevention(Methods of accident prevention: training in health and safety procedures; using health and safety procedures; use of equipment and working practices (such as safe carrying procedures); safety notices, advice; instruction from colleagues and supervisors)
- KU8.** safe working practices when working with tools and machines
- KU9.** safe working practices while working at various hazardous sites
- KU10.** where to find all the general health and safety equipment in the workplace
- KU11.** various dangers associated with the use of electrical equipment
- KU12.** preventative and remedial actions to be taken in the case of exposure to toxic materials(Exposure: ingested, contact with skin, inhaled); (Preventative action: ventilation, masks, protective clothing/ equipment); (Remedial action: immediate first aid, report to supervisor Toxic materials: solvents, flux, lead)
- KU13.** importance of using protective clothing/equipment while working
- KU14.** precautionary activities to prevent the fire accident
- KU15.** various causes of fire(Causes of fires: heating of metal; spontaneous ignition; sparking; electrical heating; loose fires (smoking, welding, etc.); chemical fires; etc.)
- KU16.** techniques of using the different fire extinguishers
- KU17.** different methods of extinguishing fire
- KU18.** different materials used for extinguishing fire(Materials: sand, water, foam, CO2, dry powder)
- KU19.** rescue techniques applied during a fire hazard
- KU20.** various types of safety signs and what they mean
- KU21.** appropriate basic first aid treatment relevant to the condition eg. shock, electrical shock, bleeding, breaks to bones, minor burns, resuscitation, poisoning, eye injuries
- KU22.** content of written accident report
- KU23.** potential injuries and ill health associated with incorrect manual handling

Qualification Pack

KU24. safe lifting and carrying practices

KU25. personal safety, health and dignity issues relating to the movement of a person by others

KU26. potential impact to a person who is moved incorrectly

Generic Skills (GS)

User/individual on the job needs to know how to:

GS1. read and comprehend basic content to read labels, charts, signages

GS2. read and comprehend basic English to read manuals of operations

GS3. read an accident/incident report in local language or English

GS4. write an accident/incident report in local language or English

GS5. question co-workers appropriately in order to clarify instructions and other issues

GS6. give clear instructions to coworkers, subordinates others

GS7. make appropriate decisions pertaining to the concerned area of work with respect to intended work objective, span of authority, responsibility, laid down procedure and guidelines

GS8. plan and organize their own work schedule, work area, tools, equipment and materials to maintain decorum and for improved productivity

GS9. remain congenial while discussing and debating issues with co-workers

GS10. follow appropriate protocols for communication based on situation, hierarchy, organizational culture and practice

GS11. ask for, provide and receive required assistance where possible to ensure achievement of work related objectives

GS12. thank co-workers for any assistance received

GS13. offer appropriate respect based on mutuality and respect for fellow workmanship and authority

GS14. identify immediate or temporary solutions to resolve delays

GS15. identify sources of support that can be availed of for problem solving for various kind of problems

GS16. seek appropriate assistance from other sources to resolve problems

GS17. report problems that you cannot resolve to appropriate authority

GS18. identify cause and effect relations in their area of work

GS19. use cause and effect relations to anticipate potential problems and their solution

Qualification Pack

Assessment Criteria

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
<i>Health and safety</i>	21	32	-	-
PC1. use protective clothing/equipment for specific tasks and work conditions (Protective clothing: leather or asbestos gloves, flame proof aprons, flame proof overalls buttoned to neck, cuffless (without folds), trousers, reinforced footwear, helmets/hard hats, cap and shoulder covers, ear defenders/plugs, safety boots, knee pads, particle masks, glasses/goggles/visors Equipment: hand shields, machine guards, residual current devices, shields, dust sheets, respirator)	1	3	-	-
PC2. state the name and location of people responsible for health and safety in the workplace	1	2	-	-
PC3. state the names and location of documents that refer to health and safety in the workplace	1	2	-	-
PC4. identify job-site hazardous work and state possible causes of risk or accident in the workplace (Hazards: sharp edged and heavy tools; heated metals; oxyfuel and gas cylinders; welding radiation; hazardous surfaces(sharp, slippery, uneven, chipped, broken, etc.); hazardous substances(chemicals, gas, oxy-fuel, fumes, dust, etc.); physical hazards(working at heights, large and heavy objects and machines, sharp and piercing objects, tools and machines, intense light, load noise, obstructions in corridors, by doors, blind turns, noise, over stacked shelves and packages, etc.) electrical hazards (power supply and points, loose and naked cables and wires, electrical machines and appliances, etc.) Possible causes of risk and accident: physical actions; reading; listening to and giving instructions; inattention; sickness and incapacity (such as drunkenness); health hazards (such as untreated injuries and contagious illness))	2	3	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC5. carry out safe working practices while dealing with hazards to ensure the safety of self and others (Safe working practices: using protective clothing and equipment; putting up and reading safety signs; handle tools in the correct manner and store and maintain them properly; keep work area clear of clutter, spillage and unsafe object lying casually; while working with electricity take all electrical precautions like insulated clothing, adequate equipment insulation, use of control equipment, dry work area, switch off the power supply when not required, etc.; safe lifting and carrying practices; use equipment that is working properly and is well maintained; take due measures for safety while working in confined places, trenches or at heights, etc. including safety harness, fall arrestors, etc.)	2	2	-	-
PC6. state methods of accident prevention in the work environment of the job role (Methods of accident prevention: training in health and safety procedures; using health and safety procedures; use of equipment and working practices (such as safe carrying procedures); safety notices, advice; instruction from colleagues and supervisors)	2	1	-	-
PC7. state location of general health and safety equipment in the workplace (General health and safety equipment: fire extinguishers; first aid equipment; safety instruments and clothing; safety installations(eg fire exits, exhaust fans))	2	3	-	-
PC8. inspect for faults, set up and safely use steps and ladders in general use (Ladder faults: corrosion of metal components, deterioration, splits and cracks timber components, imbalance, loose rungs, missing/unfixed nuts or bolts, etc.) (Ladders set up: firm/level base, clip/lash down, leaning at the correct angle, etc.)	2	3	-	-
PC9. work safely in and around trenches, elevated places and confined areas	2	3	-	-
PC10. lift heavy objects safely using correct procedures	2	2	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC11. apply good housekeeping practices at all times (Good housekeeping practices: clean/tidy work areas, removal/disposal of waste products, protect surfaces)	2	3	-	-
PC12. identify common hazard signs displayed in various areas (Various areas: on chemical containers; equipment; packages; inside buildings; in open areas and public spaces, etc.)	1	2	-	-
PC13. retrieve and/or point out documents that refer to health and safety in the workplace (Documents: fire notices, accident reports, safety instructions for equipment and procedures, company notices and documents, legal documents (eg government notices))	1	3	-	-
<i>Fire safety</i>	4	10	-	-
PC14. use the various appropriate fire extinguishers on different types of fires correctly (Types of fires: Class A: eg. ordinary solid combustibles, such as wood, paper, cloth, plastic, charcoal, etc.; Class B: flammable liquids and gases, such as gasoline, propane, diesel fuel, tar, cooking oil, and similar substances; Class C: eg. electrical equipment such as appliances, wiring, breaker panels, etc. (These categories of fires become Class A, B, and D fires when the electrical equipment that initiated the fire is no longer receiving electricity); Class D: combustible metals such as magnesium, titanium, and sodium (These fires burn at extremely high temperatures and require special suppression agents))	1	2	-	-
PC15. demonstrate rescue techniques applied during fire hazard	1	2	-	-
PC16. demonstrate good housekeeping in order to prevent fire hazards	1	3	-	-
PC17. demonstrate the correct use of a fire extinguisher	1	3	-	-
<i>Emergencies, rescue and first-aid procedures</i>	9	20	-	-
PC18. demonstrate how to free a person from electrocution	1	3	-	-

Qualification Pack

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
PC19. administer appropriate first aid to victims where required eg. in case of bleeding, burns, choking, electric shock, poisoning etc.	1	2	-	-
PC20. demonstrate basic techniques of bandaging	1	2	-	-
PC21. respond promptly and appropriately to an accident situation or medical emergency in real or simulated environments	1	2	-	-
PC22. perform and organize loss minimization or rescue activity during an accident in real or simulated environments	1	2	-	-
PC23. administer first aid to victims in case of a heart attack or cardiac arrest due to electric shock, before the arrival of emergency services in real or simulated cases	1	2	-	-
PC24. demonstrate the artificial respiration and the CPR Process	1	2	-	-
PC25. participate in emergency procedures (Emergency procedures: raising alarm, safe/efficient, evacuation, correct means of escape, correct assembly point, roll call, correct return to work)	1	3	-	-
PC26. complete a written accident/incident report or dictate a report to another person, and send report to person responsible (Incident Report includes details of: name, date/time of incident, date/time of report, location, environment conditions, persons involved, sequence of events, injuries sustained, damage sustained, actions taken, witnesses, supervisor/manager notified)	1	2	-	-
<i>Emergencies, rescue and first-aid procedures</i>	2	2	-	-
PC27. demonstrate correct method to move injured people and others during an emergency	2	2	-	-
NOS Total	36	64	-	-

Qualification Pack

National Occupational Standards (NOS) Parameters

NOS Code	CSC/N1335
NOS Name	Use basic health and safety practices at the workplace
Sector	Capital Goods
Sub-Sector	Machine Tools, Process Plant Machinery, Dies, Moulds and Press Tools, Electrical and Power Machinery, Plastics Manufacturing Machinery, Light Engineering Goods, Textile Manufacturing Machinery
Occupation	Machining
NSQF Level	3
Credits	TBD
Version	1.0
Last Reviewed Date	08/05/2025
Next Review Date	08/05/2028
NSQC Clearance Date	08/05/2025

Qualification Pack

CSC/N1336: Work effectively with others

Description

This unit covers basic etiquette and competencies that a candidate is required to possess and demonstrate in their behavior and interactions with others at the workplace. These cover areas such as communication etiquette, discipline, listening etc.

Elements and Performance Criteria

Work effectively with others

To be competent, the user/individual on the job must be able to:

- PC1.** accurately receive information and instructions from the supervisor and fellow workers, getting clarification where required
- PC2.** accurately pass on information to authorized persons who require it and within agreed timescale and confirm its receipt
- PC3.** give information to others clearly, at a pace and in a manner that helps them to understand
- PC4.** display helpful behavior by assisting others in performing tasks in a positive manner, where required and possible
- PC5.** consult with and assist others to maximize effectiveness and efficiency in carrying out tasks
- PC6.** display appropriate communication etiquette while working (Communication etiquette: do not use abusive language; use appropriate titles and terms of respect; do not eat or chew while talking (vice versa) etc.)
- PC7.** display active listening skills while interacting with others at work
- PC8.** use appropriate tone, pitch and language to convey politeness, assertiveness, care and professionalism
- PC9.** demonstrate responsible and disciplined behaviors at the workplace (Disciplined behaviors: e.g. punctuality; completing tasks as per given time and standards; not gossiping and idling time; eliminating waste, honesty, etc.)
- PC10.** escalate grievances and problems to appropriate authority as per procedure to resolve them and avoid conflict

Knowledge and Understanding (KU)

The individual on the job needs to know and understand:

- KU1.** legislation, standards, policies, and procedures followed in the company relevant to own employment and performance conditions
- KU2.** reporting structure, inter-dependent functions, lines and procedures in the work area
- KU3.** relevant people and their responsibilities within the work area
- KU4.** escalation matrix and procedures for reporting work and employment related issues
- KU5.** various categories of people that one is required to communicate and coordinate within the organization
- KU6.** importance of effective communication in the workplace

Qualification Pack

- KU7.** importance of teamwork in organizational and individual success
- KU8.** various components of effective communication
- KU9.** key elements of active listening
- KU10.** value and importance of active listening and assertive communication
- KU11.** barriers to effective communication
- KU12.** importance of tone and pitch in effective communication
- KU13.** importance of avoiding casual expletives and unpleasant terms while communicating professional circles
- KU14.** how poor communication practices can disturb people, environment and cause problems for the employee, the employer and the customer
- KU15.** importance of ethics for professional success
- KU16.** importance of discipline for professional success
- KU17.** what constitutes disciplined behavior for a working professional
- KU18.** common reasons for interpersonal conflict
- KU19.** importance of developing effective working relationships for professional success
- KU20.** expressing and addressing grievances appropriately and effectively
- KU21.** importance and ways of managing interpersonal conflict effectively

Generic Skills (GS)

User/individual on the job needs to know how to:

- GS1.** read basic terms and terminologies to accurately interpret work-related documents, labels, supervisor instructions in the local language
- GS2.** read and interpret accurate information from various relevant work instructions and records
- GS3.** write clear and legible notes to self, colleagues and seniors to pass messages, keep records, prepare to-do lists, take down instructions
- GS4.** write basic numbers, quantities and work-related terminology for operational requirements in the local language
- GS5.** interact with the supervisor appropriately (correct protocol and manner of speaking) in order to understand the basic requirements of the product, production plans, and other associated requirements
- GS6.** give clear instructions to co-workers about the type of output required and answer queries
- GS7.** display active listening skills while interacting with co-workers and others in the workplace
- GS8.** use appropriate planning to maintain a smooth relationship with fellow team members
- GS9.** take steps within ones limits of authority to initiate modification in plan if the circumstances require it
- GS10.** check that work meets customer requirements
- GS11.** deliver consistent and reliable service to internal and external customers
- GS12.** work with co-workers and supervisor to resolve any issues that threaten disruption, increase risk, cause delays or under-achievement of quality and targets as per the planned schedule

Qualification Pack

Assessment Criteria

Assessment Criteria for Outcomes	Theory Marks	Practical Marks	Project Marks	Viva Marks
<i>Work effectively with others</i>	30	70	-	-
PC1. accurately receive information and instructions from the supervisor and fellow workers, getting clarification where required	3	7	-	-
PC2. accurately pass on information to authorized persons who require it and within agreed timescale and confirm its receipt	3	7	-	-
PC3. give information to others clearly, at a pace and in a manner that helps them to understand	3	7	-	-
PC4. display helpful behavior by assisting others in performing tasks in a positive manner, where required and possible	3	7	-	-
PC5. consult with and assist others to maximize effectiveness and efficiency in carrying out tasks	3	7	-	-
PC6. display appropriate communication etiquette while working (Communication etiquette: do not use abusive language; use appropriate titles and terms of respect; do not eat or chew while talking (vice versa) etc.)	3	7	-	-
PC7. display active listening skills while interacting with others at work	3	7	-	-
PC8. use appropriate tone, pitch and language to convey politeness, assertiveness, care and professionalism	3	7	-	-
PC9. demonstrate responsible and disciplined behaviors at the workplace (Disciplined behaviors: e.g. punctuality; completing tasks as per given time and standards; not gossiping and idling time; eliminating waste, honesty, etc.)	3	7	-	-
PC10. escalate grievances and problems to appropriate authority as per procedure to resolve them and avoid conflict	3	7	-	-
NOS Total	30	70	-	-

Qualification Pack

National Occupational Standards (NOS) Parameters

NOS Code	CSC/N1336
NOS Name	Work effectively with others
Sector	Capital Goods
Sub-Sector	Machine Tools, Dies, Moulds and Press Tools, Plastics Manufacturing Machinery, Textile Manufacturing Machinery, Process Plant Machinery, Electrical and Power Machinery, Light Engineering Goods
Occupation	Machining
NSQF Level	3
Credits	TBD
Version	1.0
Last Reviewed Date	30/09/2021
Next Review Date	30/09/2024
NSQC Clearance Date	30/09/2021

Assessment Guidelines and Assessment Weightage

Assessment Guidelines

1. Criteria for assessment for the Qualification Pack will be created by CGSC.
2. Performance Criteria (PC) have been assigned marks proportional to its importance in NOS. SSC will also lay down proportion of marks for Theory and Skills Practical for each PC.
3. The assessment for the theory part will/may be based on knowledge bank of questions approved CGSC.
4. Assessment will be conducted for all compulsory NOS, and where applicable, on the selected elective/option NOS/set of NOS.
5. Assessment Agencies will create Assessor Guides comprising of Theory and Practical Assessment Set and Guidelines for each examination/training centre (as per assessment criteria below). The same will be approved by CGSC for adequacy.
6. To successfully attain Certification on the Qualification Pack, the trainee must score a minimum of 70% in each Core NOS and minimum of 50% in all non-core NOS. In addition, a candidate needs to attain a minimum overall pass percentage of 70% for certification.

Qualification Pack

7. In case of unsuccessful completion, the trainee may seek reassessment on the Qualification Pack.

Minimum Aggregate Passing % at QP Level : 70

(**Please note:** Every Trainee should score a minimum aggregate passing percentage as specified above, to successfully clear the Qualification Pack assessment.)

Assessment Weightage

Compulsory NOS

National Occupational Standards	Theory Marks	Practical Marks	Project Marks	Viva Marks	Total Marks	Weightage
CSC/N0401.Program computer numerically controlled (CNC) machines	25	75	-	-	100	80
CSC/N1335.Use basic health and safety practices at the workplace	36	64	-	-	100	10
CSC/N1336.Work effectively with others	30	70	-	-	100	10
Total	91	209	-	-	300	100

Qualification Pack

Acronyms

NOS	National Occupational Standard(s)
NSQF	National Skills Qualifications Framework
QP	Qualifications Pack
TVET	Technical and Vocational Education and Training
CNC	Computer Numerically Controlled
NC	Numerically Controlled
VMC	Vertical Machining Center
HMC	Horizontal Machining Center
CAD	Computer Aided Design
2D	2 Dimensional
3D	3 Dimensional
CO₂	Carbon Dioxide
CPR	Cardiac Pulmonary Resuscitation
ISO	International Organization For Standardization
PPE	Personal Protective Equipment

Qualification Pack

Glossary

Sector	Sector is a conglomeration of different business operations having similar business and interests. It may also be defined as a distinct subset of the economy whose components share similar characteristics and interests.
Sub-sector	Sub-sector is derived from a further breakdown based on the characteristics and interests of its components.
Occupation	Occupation is a set of job roles, which perform similar/ related set of functions in an industry.
Job role	Job role defines a unique set of functions that together form a unique employment opportunity in an organisation.
Occupational Standards (OS)	OS specify the standards of performance an individual must achieve when carrying out a function in the workplace, together with the Knowledge and Understanding (KU) they need to meet that standard consistently. Occupational Standards are applicable both in the Indian and global contexts.
Performance Criteria (PC)	Performance Criteria (PC) are statements that together specify the standard of performance required when carrying out a task.
National Occupational Standards (NOS)	NOS are occupational standards which apply uniquely in the Indian context.
Qualifications Pack (QP)	QP comprises the set of OS, together with the educational, training and other criteria required to perform a job role. A QP is assigned a unique qualifications pack code.
Unit Code	Unit code is a unique identifier for an Occupational Standard, which is denoted by an 'N'
Unit Title	Unit title gives a clear overall statement about what the incumbent should be able to do.
Description	Description gives a short summary of the unit content. This would be helpful to anyone searching on a database to verify that this is the appropriate OS they are looking for.
Scope	Scope is a set of statements specifying the range of variables that an individual may have to deal with in carrying out the function which have a critical impact on quality of performance required.

Qualification Pack

Knowledge and Understanding (KU)	Knowledge and Understanding (KU) are statements which together specify the technical, generic, professional and organisational specific knowledge that an individual needs in order to perform to the required standard.
Organisational Context	Organisational context includes the way the organisation is structured and how it operates, including the extent of operative knowledge managers have of their relevant areas of responsibility.
Technical Knowledge	Technical knowledge is the specific knowledge needed to accomplish specific designated responsibilities.
Core Skills/ Generic Skills (GS)	Core skills or Generic Skills (GS) are a group of skills that are the key to learning and working in today's world. These skills are typically needed in any work environment in today's world. These skills are typically needed in any work environment. In the context of the OS, these include communication related skills that are applicable to most job roles.
Electives	Electives are NOS/set of NOS that are identified by the sector as contributive to specialization in a job role. There may be multiple electives within a QP for each specialized job role. Trainees must select at least one elective for the successful completion of a QP with Electives.
Options	Options are NOS/set of NOS that are identified by the sector as additional skills. There may be multiple options within a QP. It is not mandatory to select any of the options to complete a QP with Options.