




- Comments:
1. Check assemblability.
 2. Perform Assembly as shown in drawing.
 3. Make a trial motions of individual mechanisms and moving parts in order to verify the correctness of installation.
 4. Protect against damage and corrosion on time waiting for the main installation.

2	1	Bar 18x $\varnothing 50/\varnothing 35$	DIN-EN 10060	0	1.4301	0.09	
3	1	Plate 2x45x130	DIN-EN 10029	0	1.4301	0.09	
1	1	Plate 8x110x152,5	DIN-EN 10029	0	1.4301	0.7	Ex. Left
Item	Qty.	Name of part	Drawing number, standard	Rev.	Material	Weight Ipcs. kg	Comments
Investor:							
		Weight 1 set 0,9 kg	Drawing name Conveyor Belt 900mm Conveyor Body Drum support 2				
Engin.	2016-04-29	papacad	Drawing number CB-900 01.02.00.00				Revision 0
Draw.	2016-04-29	papacad					
Check.	2016-04-29	papacad					
Ver.	2016-04-29	papacad					
Appr.	2016-04-29	papacad					Sheet 1 / 1
papacad 3D & 2D CAD PROJECTS free & purchase			www.papacad.com		Scale 1 : 1	Format A1	