








- Comments:
1. Check assemblability.
 2. Perform Assembly as shown in drawing.
 3. Make a trial motions of individual mechanisms and moving parts in order to verify the correctness of installation.
 4. Protect against damage and corrosion on time waiting for the main installation.

7	2	Retaining rings for shaft	DIN 471 – 20x1,2	0	A2	0	
6	2	Parallel Key A 8 x 7 x 36	DIN 6885 – A 8 x 7 x 36	0	1.4301	0.02	
5	1	Parallel Key A 6 x 6 x 56	DIN 6885 – A 6 x 6 x 56	0	1.4301	0.02	
4	2	Deep groove bearing 6004–2RS1	SKF	0		0.01	
3	2	Distance ring	CB–900 02.00.00.03	0	1.4301	0.01	
2	1	Drum	CB–900 02.00.00.02	0	PA 6	1.56	
1	1	Drum Shaft	OCB–900 02.00.00.01	0	1.4301	1.4	
Item	Qty.	Name of part	Drawing number, standard	Rev.	Material	Weight Ipcs. kg	Comments

Investor:							
		Weight 1 set 3,0 kg	Drawing name Conveyor Belt 900mm Main Assembly Drive Drum				
Engin.	2008-08-22	papacad	Drawing number CB–900 02.00.00.00				Revision 0
Draw.	2008-08-22	papacad					
Check.	2016-05-14	papacad					
Ver.		papacad					
Appr.		papacad					Sheet
papacad 3D & 2D CAD PROJECTS free & purchase		www.papacad.com	Scale 1 : 1	Size A1	1 / 1		