





- Comments:
1. Check assemblability.
 2. Perform Assembly as shown in drawing.
 3. Make a trial motions of individual mechanisms and moving parts in order to verify the correctness of installation.
 4. Protect against damage and corrosion on time waiting for the main installation.

4	2	Retaining ring for shaft	DIN 471 – 15x1	0	Steel	0		
3	2	Deep grrove bearing 61802–2Z	SKF	0		0		
2	1	Roll	CB–900 04.00.00.02	0	PA 6	0.13		
1	1	Shaft	CB–900 04.00.00.01	0	1.4301	0.4		
Item	Qty.	Name of part	Drawing number, standard	Rev.	Material	Weight 1pcs. kg	Comments	
Inwestor:								
		Weight 1 set 0.5 kg	Drawing name Conveyor Belt 900mm Main Assembly Supporting Roll					
Engin.	2016-06-04	papacad						
Draw.	2016-06-04	papacad						
Check.	2016-06-04	papacad						
Ver.	2016-06-04	papacad						
Appr.	2016-06-04	papacad	Drawing number CB–900 04.00.00.00				Revision 0	
papacad 3D & 2D CAD PROJECTS free & purchase			www.papacad.com			Scale 2 : 1	Size A2	Sheet 1 / 1