1 2 3 4 5 6 7




## LPCXpresso55SXX.PrjPcb

Elaborated by: Eduardo Teofilo Checked by: José Ogando

Revision: A2 Last revision date: 18/06/2019

## Change Log 25-04-2018 Power supply of Link2 circuitry replaced from 3.3v to 2.5v - Package of LPC5500 changed from BGA to HLQFP - Added 330hms Resistor for DP and DM pins of USB0 FS - Added TestPoints for U2 debug signals 08-05-2018 - Tied P0 5 to P7 Pin7 - SDO Pull-ups tied to VDD\_SD - Added Pull-up for P0\_5-ISP1 - Added notes and descriptions - Added jumper to P25 - Added connections to P19 - Added debug probe for U2 - Removed P22 Debug probe for U1 - Changed Y3 form 12MHz to 16Mhz 16-05-2018 - Removed external battery support - Added Support for 1.1v external power supply 21-05-2018 - Exchange of functions between PIO1\_5 and PIO1\_7 25-05-2018 -Changed function of PIOO\_15, PIOO\_18, PIOO\_22, PIOO\_28 and PIO1\_13 -Added Cpacitors C97, C100 -Fixed values of R82, R86 -Changed PN of U8, U9, U10 -Removed U4 31-05-2018 -Changed P14 2X1 to 2X2 header 1-06-2018 -Removed U17 6-06-2018 29-08-2018 - Changed U10 XC6504A251MR-G to XC6223H251MR-G 05-11-2018 -Added P29, R85 05-11-2018 -L10 Replaced from CBC2518T4R7M to TDK MLZ2012M4R7HT000 15-11-2018 -R120 and R121 were changed from 100K to 2.2k -Fix SDA connections -Updated Revision to A1 29-05-2019 -Added LPC55S69 and LPC55S28 variants -Changed J11, J12, R73, R114, R128 to DNI -Restore P20 to variants -Changed R74 from 100K to 330k -Added variants to silk screen -Updated Revision to A2



9

1

2

4

